

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYSUBMIT IN TRIPLICATE*
(Other instructions reverse side)Form approved.
Budget Bureau No. 42-R1424.

NMOCC - ARTESIA

NMOCC - HOBBS

BLM - SANTA FE

SUMMARY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT" for such proposals.

5. LEASE DESIGNATION AND SERIAL NO.

NM-046153-A

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

MILLER, Federal

9. WELL NO.

1

10. FIELD AND POOL, OR WILDCAT

WILDCAT

11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA

34-7-31 NMPM

12. COUNTY OR PARISH 13. STATE

CHAVES

N.M.

1. OIL WELL ☐ GAS WELL ☐ OTHER ☒ Drilling2. NAME OF OPERATOR
PAN AMERICAN PETROLEUM CORPORATION3. ADDRESS OF OPERATOR
BOX 68, HOBBS, N. M. 882404. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*
See also space 17 below.)
At surface

660' FSL x 660' FEL SEC. 34 (Unit P, SE 1/4 SE 1/4)

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐FRACTURE TREAT ☐SHOOT OR ACIDIZE ☐REPAIR WELL ☐(Other) ☐PULL OR ALTER CASING ☐MULTIPLE COMPLETE ☐ABANDON* ☐CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☒FRACTURE TREATMENT ☐SHOOTING OR ACIDIZING ☐(Other) ☒ SpuddingREPAIRING WELL ☐ALTERING CASING ☐ABANDONMENT* ☐(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report (and Log form).)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Cactus Drilling Co., spudded 11" hole 10:30 AM, 3-15-67.
8 5/8" OD 24" J-55 STC Casing was set @
465' w/ 300 sq. Neat. Cement circulated.
After WOC 18 hours tested casing w/ 1000 psi
for 30 minutes. Test O.K.
Reduced hole to 7 7/8" @ 465' and resumed
drilling.

RECEIVED

MAR 22 1967

U. S. GEOLOGICAL SURVEY
MOSWELL, NEW MEXICO

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE

AREA SUPERINTENDENT

DATE

3-17-67

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

0 - 4-USGS-RDS

1-MSW

1-SUSP

1-RRY

*See Instructions on Reverse Side

ACCEPTED FOR RECORD

J. N. Luthersland
District Engineer