

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN TRIPLICATE*
(Other instructions on reverse side)

Form approved.
Budget Bureau No. 42-R1424.

NMOC - ARIZONA
NMOCC - HOBBS
BLM - SANTA FE

SUMMARY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

MAR 7 1967

6. LEASE DESIGNATION AND SERIAL NO.

NM-0177517

9. INDIAN, ALLOTTEE OR TRIBAL NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

CATO B Federal

9. WELL NO.

3

10. FIELD AND POOL, OR WILDCAT

CATO San Andres

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA

23-8-30 NMPM

12. COUNTY OR PARISH

CHAVES

13. STATE

N.M.

1. OIL WELL ☐ GAS WELL ☐ OTHER ☒ Drilling

2. NAME OF OPERATOR
PAN AMERICAN PETROLEUM CORPORATION

3. ADDRESS OF OPERATOR
BOX 68, HOBBS, N. M. 88240

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*
See also space 17 below.)
At surface

660' FNL x 660' FWL, Sec. 23 (Unit D, NW/4 NW/4)

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, OM, etc.)

16.

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other) Spudding

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

Chico Drilling Co. spudded 12 1/4" hole 2 PM, 3/14/67.
8 5/8" OD 24" J-55 casing was set @ 457' w/ 300 ft.
neat. Cement circulated. After 740 C
18 hours, tested casing w/ 1000 psi for 30
minutes. Test O.K.

Reduced hole to 7 7/8" @ 457' and resumed
drilling.

RECEIVED
MAR 17 1967
U. S. GEOLOGICAL SURVEY
ROSWELL, NEW MEXICO

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE

AREA SUPERINTENDENT

DATE

3-16-67

(This space for Federal or State office use)

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

TITLE

DATE

04- USGS - ROS
1- NSW
1- SUSP
1- RRY

*See Instructions on Reverse Side

ACCEPTED FOR RECORD

J. W. Sutherland
District Engineer