

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

SUBMIT IN TRIPLICATE  
(Other instructions on reverse side)

Form approved  
Bureau of Land Management No. 42 R1424

NMOCC - ARTESIA  
NMOCC - HOBBS  
BLM - SANTA FE

SUNDRY NOTICES AND REPORTS ON WELLS

Use this form for proposals to drill or to deepen or plug back to a different reservoir.  
Use "APPLICATION FOR PERMIT—" for such proposals.

LEASE DESIGNATION AND SERIAL NO.  
**NM-0177517**  
OWNER, ALLOTTEE OR TRUSTEES NAME

APR 1967

1. ☐ OIL WELL ☐ GAS WELL ☒ OTHER **DRILLING**

2. NAME OF OPERATOR  
**PAN AMERICAN PETROLEUM CORPORATION**

3. ADDRESS OF OPERATOR  
**BOX 68, HOBBS, N. M. 88240**

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.  
See also space 17 below.)  
At surface  
**1980' FSLY 660' FWL Sec 15 (UNIT L, NW 1/4 SW 1/4)**

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME  
**CATO "A" Federal**

9. WELL NO.  
**2**

10. FIELD AND POOL, OR WILDCAT  
**CATO San Andres**

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA  
**15-8-30 NMPM**

12. COUNTY OR PARISH  
**CHAVES**

13. STATE  
**N.M.**

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐  
FRACTURE TREAT ☐  
SHOOT OR ACIDIZE ☐  
REPAIR WELL ☐  
(Other) ☐

PULL OR ALTER CASING ☐  
MULTIPLE COMPLETION ☐  
ABANDON\* ☐  
CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐  
FRACTURE TREATMENT ☐  
SHOOTING OR ACIDIZING ☐  
(Other) ☐

REPAIRING WELL ☐  
ALTERING CASING ☐  
ABANDONMENT\* ☐

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

Cactus Arly Co spudded 11" hole 10:30AM 4-2-67.  
8 7/8" OD 24" J-55 Casing was set @ 455' w/ 300 sq.  
Incor. near. Cement circulated. After  
WOC for 18 hours, tested casing w/ 1000 psi  
for 30 minutes. Test O.K.  
Reduced hole to 7 7/8" @ 455 and resumed  
drilling.

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE **AREA SUPERINTENDENT**

DATE **4-4-67**

(This space for Federal or State office use)

APPROVED BY  
CONDITIONS OF APPROVAL, IF ANY:

TITLE **ACCEPTED FOR RECORD**

DATE

**J. N. Luthers**  
District Engineer

\*See Instructions on Reverse Side

0+ 4-USGS-R05  
1-NSW  
1-SUSD  
1-RRY