

Form 9-321
(May 1968)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN TRIPLICATE
(Other instructions on reverse side)

Form approved.
Budget Bureau No. 42-R1424.

6. LEASE DESIGNATION AND SERIAL NO.

NM-0354427-A

7. IF INDIAN, ALLOTTEE OR TRIBE NAME

SUMMARY NOTICES AND REPORTS ON WELLS

NM0000 - AMERINDIA
NM0000 - HOBBS
BLM - SANTA FE

Do not use this form for proposals to drill or to deepen or plug back to an adjacent reservoir.
Use "APPLICATION FOR PERMIT" for such proposals.

1. OIL WELL ☐ GAS WELL ☐ OTHER Drilling

2. NAME OF OPERATOR

PAN AMERICAN PETROLEUM CORPORATION

3. ADDRESS OF OPERATOR

BOX 68, HOBBS, N. M. 88240

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*
See also space 17 below.)
At surface

660' FNL x 1980' FEL, Sec. 23 (Unit B, NW/4 NE/4)

14. PERMIT NO.

15. ELEVATIONS (Show whether DP, RT, GM, etc.)

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

CATO "D" Federal

9. WELL NO.

10. FIELD AND POOL, OR WILDCAT

CATO San Andres

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA

23-8-30 NM PM

12. COUNTY OR PARISH

CHAVES N.M.

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

FULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON*

CHANGE PLANS

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Chico Dry Co, spudded 12 1/4" hole 5:PM 4-10-67.
On 4-11-67, 8 1/8" OD 24" J-55 casing set @ 447' w/
300 sf. Incep. neat. Cement circulated. After 70C
18 hours, tested casing w/ 750 psi. for 30 minutes,
Test OK.

Reduced hole to 7 7/8" @ 447' and resumed drilling

ACCEPTED FOR RECORD

J. N. Sutherland
District Engineer

18. I hereby certify that the foregoing is true and correct

SIGNED

AREA SUPERINTENDENT

DATE

4-12-67

(This space for Federal or State office use)

APPROVED BY
CONDITIONS OF APPROVAL, IF ANY:

TITLE

DATE

044- USGS-205
1- NSO
1- SUGD
1- RRY

*See Instructions on Reverse Side