

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEYSUBMIT IN TRIPLI  
(Other instructions  
verse side)TE-  
TC-Form approved.  
Budget Bureau No. 42-11424

5. LEASE DESIGNATION AND SERIAL NO.

NM-0448628

6. IF INDIAN, ALLOTTEE OR TOMB NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

CATO "C" Federal

9. WELL NO.

2

10. FIELD AND POOL, OR WILDCAT

CATO San Andres

11. SEC., T., R., M., OR BLM, AND  
SURVEY OR AREA

14-8-30 NMPM

12. COUNTY OR PARISH 13. STATE

CHAVES

N.M.

## SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to different reservoir.  
Use "APPLICATION FOR PERMIT" for such proposals.)1. OIL WELL ☐ GAS WELL ☐ OTHER ☒ Drilling

2. NAME OF OPERATOR

PAN AMERICAN PETROLEUM CORPORATION

3. ADDRESS OF OPERATOR

BOX 68, HOBBS, N. M. 88240

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.  
See also space 17 below.)  
At surface

660' FSL x 1980' FEL, Sec. 14 (O, SW 1/4 SE 1/4)

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

## NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐FRACTURE TREAT ☐SHOOT OR ACIDIZE ☐REPAIR WELL ☐

(Other)

PULL OR ALTER CASING ☐MULTIPLE COMPLETE ☐ABANDON\* ☐CHANGE PLANS ☐

## SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☒FRACTURE TREATMENT ☐SHOOTING OR ACIDIZING ☐


(Other)

REPAIRING WELL ☐ALTERING CASING ☐ABANDONMENT\* ☒(Note: Report results of multiple completion on Well  
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

Chico Drilling Co. spudded 12 1/4" hole 2:15 PM 6-3-67.  
At 10:45 PM 8 5/8" OD 24" J-55 casing was set @  
284' w/ 250 P4. 2% cal. circ. 40 cu. cement.  
After 1400 18 hours, tested casing w/ 700  
psi for 30 minutes. Test O.K.

Reduced hole to 7 7/8" @ 284' and resumed  
drilling.

NM000 - ARTESIA  
NM000 - HOBBS  
BLM - SANTA FE

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE

AREA SUPERINTENDENT

DATE

(This space for Federal or State office use)

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

TITLE

DATE

01 4- USGS. ROSWELL  
1- NSW  
1- SUSP  
1- RRY

\*See Instructions on Reverse Side

ACCEPTED FOR RECORD

Eddie R. Wyatt  
Acting District Engineer