

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYSUBMIT IN TRIPL
(Other instructions on reverse side)Form approved
Budget Bureau No. 42 R1121

NMDC - ARTESIA

NMDC - HOBBS

BLM - SANTA FE

SUNDARY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use "APPLICATION FOR PERMIT" for such proposals.

5. LEASE DESIGNATION AND SERIAL NO.

NM-046153-A

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

M '67

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

MILLER Federal

9. WELL NO.

5

10. FIELD AND POOL, OR WITDCAL

Tom-Tom San Ant.

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA

34-7-31 NMPM

12. COUNTY OR PARISH 13. STATE

CHAVES N.M.

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐

2. NAME OF OPERATOR

PAN AMERICAN PETROLEUM CORPORATION

3. ADDRESS OF OPERATOR

BOX 68, HOBBS, N. M. 88240

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.)
At surface

1980' FNL x 1980' FWL Sec. 34 (UNIT F, SEE/4 NW/4)

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

4326' R.D.B.

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐FRACTURE TREAT ☐SHOOT OR ACIDIZE ☐REPAIR WELL ☐(Other) ☐PULL OR ALTER CASING ☐MULTIPLE COMPLETE ☐ABANDON* ☐CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☒FRACTURE TREATMENT ☐SHOOTING OR ACIDIZING ☐(Other) ☒REPAIRING WELL ☐ALTERING CASING ☐ABANDONMENT* ☐

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

On 8-16-67, 4 1/2" OD 9.5# J-55 casing was set @ 4050 (TD) w/ 300 yd. Incon meat. Tested casing w/ 2000 psi for 30 minutes. Test O.K. Perforated intervals 3878'-3928'; 36'-74' w/ 2JSPF. Acidized w/ 5000 gal 28%. Evaluated.

PT. Pumped 40 BBL x 158 BW in 24 hours. Cgr. 25.6° GOR 280.

TD-4050

PBD-4010

TDA-3878 San Ant.

COMP-8-29-67

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE

AREA SUPERINTENDENT

DATE

8-29-67

(This space for Federal or State office use)

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

TITLE

DATE

ON 4-USGS ROS

1-NSW

1-SUSP

1-UNION TEXAS

2-T&P

ACCEPTED FOR RECORD

J. N. Lanthier

District Engineer

See Instructions on Reverse Side

RECEIVED

AUG 30 1967

U. S. GEOLOGICAL SURVEY
NEW MEXICO