

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYSUBMIT IN TRIPL
(Other instructions
verse side)

FE

Form approved.
Budget Bureau No. 42-R1424

BLM - SANTA FE

SUMMARY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)LEASE DESIGNATION AND SERIAL NO.
NW-046153-A

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

MILLER Federal

9. WELL NO.

5

10. FIELD AND POOL, OR WILDCAT

Tom-Tom San And Est.

11. SEC., T., R., M., OR B.M. AND
SURVEY OR AREA

34-7-31 NMPM

12. COUNTY OR PARISH 13. STATE

1. OIL WELL ☐ GAS WELL ☐ OTHER ☒ Drilling

2. NAME OF OPERATOR

PAN AMERICAN PETROLEUM CORPORATION

3. ADDRESS OF OPERATOR

BOX 68, HOBBS, N. M. 88240

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.
See also space 17 below.)
At surface

1980' FNL x 1980' FWL Sec. 34 (UNIT F, SE/4 NW/4)

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

4326' RDB

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐FRACTURE TREAT ☐SHOOT OR ACIDIZE ☐REPAIR WELL ☐(Other) ☐PULL OR ALTER CASING ☐MULTIPLE COMPLETE ☐ABANDON* ☐CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐FRACTURE TREATMENT ☐SHOOTING OR ACIDIZING ☐(Other) ☐REPAIRING WELL ☐ALTERING CASING ☐ABANDONMENT* ☐(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any
proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones perti-
nent to this work.)

Cactus Drilling Co. spudded 12 1/4" hole, 11 PM
8-9-67. 8 5/8" OD 2 1/2" J-55 casing was set
@ 360' w/ 300 #4 Incon + 2% calk.* Cement circ.
After 400 12 hours, tested csg w/ 1000
psi for 30 minutes. Tested OK.

Reduced hole to 7 7/8" @ 360 and resumed drilling.

* 450 CF EST VOL

85° EST TEMP OF SLURRY

70° EST FORM. TEMP.

750 psi. EST STRENGTH CMT @ TEST

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE

DATE

Area Engineer 8-10-67

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

014 NSGS-ROS
1- NSW
1- SUSP
1- RRY
1- UNION TEXAS
2- TP

*See Instructions on Reverse Side

ACCEPTED FOR RECORD

District En.