

UNITED STATES
DEPARTMENT OF THE INTERIORSUBMIT IN TRIPLICATE
(Other instructions on reverse side)Form approved.
Budget Bureau No. 42-R14.1

NM000 - ARTESIA

☐ GEOLOGICAL SURVEY

NM000 - SUNDRY NOTICES AND REPORTS ON WELLS

BLM - (Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use "APPLICATION FOR PERMIT" for such proposals.)

5. LEASE DESIGNATION AND SERIAL NO.

NM-0142233

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

CROSBY "A" Federal

9. WELL NO.

2

10. FIELD AND POOL, OR WILDCAT

CATO San Andres

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA

8-8-30- NMPM

12. COUNTY OR PARISH 13. STATE

CHAVES

N.M.

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐

2. NAME OF OPERATOR

PAN AMERICAN PETROLEUM CORPORATION

3. ADDRESS OF OPERATOR

BOX 68, HOBBS, N. M. 88240

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.)
At surface

1980' FSL x 660 FEL, Sec 8 (UNIT I, NE 1/4 SE 1/4)

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

4040' R.D.3.

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

In accordance w/ Form 9-331 dated 10-27-67, remedial work performed as follows:

Drilled & cleaned out to TD 3351. Perforated intervals 3313-18; 23-30' w/ 25SPF. Acidized w/ 3000 gal 20%.

Swabbed and evaluated. Recovered No-oil.

Gas flow @ rate of 2 MMCFPD. Set BPO 3225 and capped w/ 15' cement. Reran tubing & rods and restarted to production.

Pres. Test 38 box 4 BW 24 hr. pmp
After 957 37 box 7 BW 24 hr. pmp.

OC - 10-29-67
Comp. 11-10-67

TD - 3351'
PBD - 3210'

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE

AREA SUPERINTENDENT

DATE

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

24-UGS-205

1-NSIO

1-SUSP

1-TSP

1-ROD

ACCEPTED FOR RECORD

J. N. Lathala

*See Instructions on Reverse Side

RECEIVED

NOV 15 1967

U. S. GEOLOGICAL SURVEY
ROSWell, NEW MEXICO