

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN TRIPL
(Other instructions on re-
verse side)

Form approved.
Budget Bureau No. 42-R1124.

NMOCC - ARTESIA
NMOCC - HOBBS
BLM - SANTA FE

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT" for such proposals.)

5. LEASE DESIGNATION AND SERIAL NO.
NM-0142233

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

CROSBY 'A' Fed

9. WELL NO.

2

10. FIELD AND POOL, OR WILDCAT

CATO San Andres

11. SEC. T. R. M. OR B.L. AND
SURVEY OR AREA

8-8-30 NM PM

12. COUNTY OR PARISH

CHAUES

13. STATE

N.M.

1. OIL ☒ CAR ☐ OTHER ☐
WELL WELL

2. NAME OF OPERATOR

PAN AMERICAN PETROLEUM CORPORATION

3. ADDRESS OF OPERATOR

BOX 68, HOBBS, N. M. 88240

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*
See also space 17 below.)

At surface

1980' FSL x 660' FEL Sec. 8 (UNIT I, NE 1/4 SE 1/4)

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

4040' RDB

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHUT-IN OR ACIDIZING

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

Completion

(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE FINISHED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any
proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones perti-
nent to this work.)

On 9-11-67, 4 1/2" OD 9.5 #1-55 Casing was
set @ 3351' w/ 300 #4 Incon meat. Tested
casing w/ 2000 psi for 30 minutes. Test O.K.
Perforated intervals 3261-70, 3274-91, 94-97,
w/ 2 1/2" SPF. Acidized w/ 3000 gal 28% acid.
Spurred 3261-97 w/ 150 #4 cement. PBD - 3200'.
Perforated 3114-60 w/ 2 1/2" SPF. Acidized w/ 8000 gal
28% acid.

PT-Swab 6580 x 36 BLW 24 hours. 43 MCFG. GORBB C_{25.2}

TD - 3351'

PBD - 3200'

TPSI 3114' Comp 9-20-67.

I hereby certify that the foregoing is true and correct

SIGNED *E. J. Lohrey*

TITLE AREA SUPERINTENDENT

DATE 9-20-67

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE

COPIES OF APPROVAL, IF ANY:

ACCEPTED FOR RECORD

J. N. Luthalant
District Engineer

*See Instructions on Reverse Side

RECEIVED
OCT 1 1967
GEOLOGICAL SURVEY