

WABCC - ARTESIA  
NMOCC - HOBBS  
BLM - SANTA FE

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

SUBMIT IN TRIPLICATE  
(Other instructions on reverse side)

Form approved.  
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

NH-025519

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

117

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

WHITE Federal

9. WELL NO.

1

10. FIELD AND POOL, OR WILDCAT

WILDCAT

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA

13-9-30 NMPM

12. COUNTY OR PARISH 12. STATE

CHAVES N.M.

SUMMARY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use "APPLICATION FOR PERMIT--" for such proposals.

OIL WELL ☐ GAS WELL ☐ OTHER ☒ DRILLING

2. NAME OF OPERATOR

PAN AMERICAN PETROLEUM CORPORATION

3. ADDRESS OF OPERATOR

BOX 68, HOBBS, N. M. 88240

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.\* See also space 17 below.)

At surface

660' FSL \* 660' FWL, Sec. 13, (Unit 19, SW 1/4 SW 1/4)

14. PERMIT NO.

15. ELEVATIONS (Show whether DE, RT, OR, etc.)

4137' R.D.B.

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐

FRACTURE TREAT ☐

SHOOT OR ACIDIZE ☐

REPAIR WELL ☐

(Other) ☐

PULL OR ALTER CASING ☐

MULTIPLE COMPLETE ☐

ABANDON\* ☐

CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☒

FRACTURE TREATMENT ☐

SHOOTING OR ACIDIZING ☐

(Other) ☐

REPAIRING WELL ☐

ALTERING CASING ☐

ABANDONMENT\* ☐

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

On 11-11-67, 9 5/8" OD 32.3-40" H-40 J-55 Casing was set @ 4980' w/ 2505x Drcon 4% Hel + 500 x 4. Neat. All cement sack saturated. After WOC 18 hours, tested casing w/ 1800 psi for 30 minutes. Test O.K. Reduce hole to 8 3/4" @ 4980' and resumed drilling.

RECEIVED

NOV 15 1967

U. S. GEOLOGICAL SURVEY  
ROSWELL, NEW MEXICO

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE

AREA SUPERINTENDENT

DATE

11-14-67

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

01-4 UGGS-RDS  
1-NSW  
1-SUSP  
1-RR4

ACCEPTED FOR RECORD

J. W. Luthar

District Engineer

\*See Instructions on Reverse Side