

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYSUBMIT IN TRIPLICATE
(Other instructions
verse side)Form approved.
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

NM 0346362 (b)

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Woodman Federal

9. WELL NO.

3

10. FIELD AND POOL, OR WILDCAT

Cato San Andres

11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA

28-T8S-30E

12. COUNTY OR PARISH

Chaves

13. STATE

N.M.

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)1. OIL WELL ☒ GAS WELL ☐ OTHER ☐ Plug & Abandon

2. NAME OF OPERATOR

Atlantic Richfield Company

3. ADDRESS OF OPERATOR

P. O. Box 1710, Hobbs, New Mexico 88240

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*
See also space 17 below.)
At surface

660' FNL & 660' FEL (Unit Letter A)

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

4145' GR

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐FRACTURE TREAT ☐SHOOT OR ACIDIZE ☐REPAIR WELL ☐(Other) ☐PULL OR ALTER CASING ☐MULTIPLE COMPLETE ☐ABANDON* ☐CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐FRACTURE TREATMENT ☐SHOOTING OR ACIDIZING ☐(Other) Plug & Abandon ☒REPAIRING WELL ☐ALTERING CASING ☐ABANDONMENT* ☐(Note: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

The above well was plugged and abandoned in the following manner:

Rigged up and install BOP. Made trip w/bit and scraper to 3400'. OK. WIH w/4 1/2" cmt retr on 2-3/8" tbg set @ 3400'. Displaced 70 sx Cl C, 4% gel below retr w/300# press. Spotted 5 sx on top. Circ hole w/9# gelled mud. W/tbg OE spotted 75 sx Cl C, 4% gel, 2300-2600'. Cut 4 1/2" csg. @ 2250', unable to pull. Cut 4 1/2" csg @ 2170' and rec. 2170'. Spotted 50 sx Cl C, .4% HR-4 2060-2260' across 4 1/2" csg stub. Spotted 40 sx Cl C neat cmt plug across top of salt @ 1000'. Spotted 50 sx Cl C neat across csg 8-5/8" csg shoe 115-315'. Spotted 10 sx cmt plug a surf. Erected dry hole marker. P&A eff: 05/08/75. Final Report.

Your office to be notified when location is cleaned & levelled in accordance w/USGS & BLM surface abandonment requirements.

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE Dist Drlg. Supv.

DATE May 12, 1975

(This space for Federal or State office use)

APPROVED BY
CONDITIONS OF APPROVAL, IF ANY:

TITLE

DATE

*See Instructions on Reverse Side

RECEIVED
OCT 3 1975
D. C. C.
ARTESIA, OFFICE