

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN TRIPLICATE
(Other instructions on reverse side)

Form approved.
Budget Bureau No. 42-R1424.

NMOC - ARTESIA

NMOC - ARTESIA

DEPT.

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT" for such proposals.)

6. LEASE DESIGNATION AND SERIAL NO.

NM-0403706

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

ABKO Federal

9. WELL NO.

10. FIELD AND POOL, OR WILDCAT

CATO San Ananias

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA

10-8-30 NMPM

12. COUNTY OR PARISH

CHAVES

13. STATE

N.M.

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐

2. NAME OF OPERATOR

PAN AMERICAN PETROLEUM CORPORATION

3. ADDRESS OF OPERATOR

BOX 68, HOBBS, N. M. 88240

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.
See also space 17 below.)
At surface

660' FNL x 1980' FEL. Sec 10 (UNIT B NW 1/4 NE 1/4)

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

4088' R.D.B.

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

11-27-67. 4 1/2" OD 9.5 #1-55 Casing was set @ 3440 (TD) w/ 300 ft. Snorey neck. Tested casing w/ 2100 psi for 30 min. Test. O.C. (PBD, 3412')

Perforated intervals 3292-96, 3304-13, 16-25, 60-76, 83-88, 94-00; w/ 215PF.

Acidized w/ 6000 gal 20% Acid.

Evaluated.

On PT. Swab 5980 x 37BLW in 24 hours. Cgr. 26° 60R, NA.

RECEIVED
DEC 7 1967
U.S. GEOLOGICAL SURVEY
NEW MEXICO

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE

DATE

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

014-USGS-R03
1-NSW
1-SUSP
1-RRY

ACCEPTED FOR RECORD

J. N. Luthala
District Engineer

*See Instructions on Reverse Side