

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN TRIPPLICATE*
(Other instructions on reverse side)

Form approved.
Budget Bureau No. 42-41101

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT" for such proposals.)

1. ☒ OIL WELL ☐ GAS WELL ☐ OTHER		5. LEASE DESIGNATION AND SERIAL NO. NM-022636
2. NAME OF OPERATOR Shell Oil Company		6. IF INDIAN, ALLOTTEE OR TRIBE NAME
3. ADDRESS OF OPERATOR P. O. Box 1509, Midland, Texas 79701		7. UNIT AGREEMENT NAME
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface 1980' FSL & 560' <u>W</u> <u>FEL</u> , Section 34, T-8-S, R.30-E		8. FARM OR LEASE NAME Hodges Federal B
14. PERMIT NO.		9. WELL NO. 3
15. ELEVATIONS (Show whether DF, RT, GR, etc.) 3620'		10. FIELD AND POOL, OF WILDCAT Cato (San Andres)
		11. SEC., T., R., M., OF BLM. AND SURVEY OR AREA Sec. 34, T-8-S, R-30-E, NMMP
		12. COUNTY OR PARISH 13. STATE Chaves New Mexico

18. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐	PULL OR ALTER CASING ☐
FRACTURE TREAT ☐	MULTIPLE COMPLETE ☐
SHOOT OR ACIDIZE ☐	ABANDON* ☐
REPAIR WELL ☐	CHANGE PLANS ☐
(Other) ☐	

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐	REPAIRING WELL ☐
FRACTURE TREATMENT ☐	ALTERING CASING ☐
SHOOTING OR ACIDIZING ☐	ABANDONMENT* ☐
(Other) ☒ Test for Casing Leak	

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

1. Pulled rods, pump and tubing.
2. Ran 2" tbg with packer to 3432'. Loaded annulus above packer with 19 barrels water.
3. Survey showed perfs (3455-3510') taking water.
4. Reran tbg with 4 1/2" Baker retrievable bridge plug. Set plug at 3500'.
5. Placed on production.

RECEIVED
SEP 12 1969
U. S. GEOLOGICAL SURVEY
ALBUQUERQUE, NEW MEXICO
RECEIVED
SEP 9 1969
U. S. GEOLOGICAL SURVEY
ALBUQUERQUE, NEW MEXICO

18. I hereby certify that the foregoing is true and correct

SIGNED M. O. Traugott M. O. Traugott, District Engineer, Petrophysical Engr.

DATE 9/5/69

(This space for Federal or State office use)

APPROVED BY _____
CONDITIONS OF APPROVAL, IF ANY:

TITLE _____

RECEIVED

SEP 15 1969

*See Instructions on Reverse Side

ACCEPTED FOR RECORD PURPOSES

SEP 12 1969

SEP 12 1969

District Engineer

ACTING

D. C. C.
ALBUQUERQUE, OFFICE