

Form 9-331
(May 1963)UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYSUBMIT IN TRIPLICATE*
(Other instructions on reverse side)Form approved.
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

NM-0354427-A

6. IF INDIAN, ALLOTED OR TRIBE NAME

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill on, to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT" for such proposals.)

1.

OIL WELL ☒ GAS WELL ☐ OTHER ☐

2. NAME OF OPERATOR

PAN AMERICAN PETROLEUM CORPORATION

3. ADDRESS OF OPERATOR

BOX 68, HOBBS, N. M. 88240

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*
See also space 17 below.)

At surface

330 FNL x 990 FEL Sec. 23 (Unit A, NE 1/4 NE 1/4)

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

4197' R. D. B.

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

CATO "D" Federal

9. WELL NO.

3

10. FIELD AND POOL, OR WILDCAT

CATO San Andres

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA

23-8-30 NM PM

12. COUNTY OR PARISH 13. STATE

CHAVES N.M.

16.

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐FRACTURE TREAT ☐SHOOT OR ACIDIZE ☐REPAIR WELL ☐(Other) ☐PULL OR ALTER CASING ☐MULTIPLE COMPLETE ☐ABANDON* ☐CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☒FRACTURE TREATMENT ☐SHOOTING OR ACIDIZING ☐(Other) ☐REPAIRING WELL ☐ALTERING CASING ☐ABANDONMENT* ☐

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

On 6-7-69. 4 1/2" OD 9.5# J-55 Casing was set @ 3631' w/ 350sx Incon meat. Tested casing w/ 1600 psi for 30 min. Test O.K. After MOC apply 72 hours, perforated intervals 3562-3615 w/ 215PF. Acidized w/ 3000 gal 15%. Evaluate.

PT. Amp 480 x 124 BW 24 hr. BORNA. Cgs. 26.

RECEIVED
JUL 18 1969
U. S. GEOLOGICAL SURVEY
ARTESIA, NEW MEXICO

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE

AREA SUPERINTENDENT

DATE

JUL 16 1969

(This space for Federal or State office use)

APPROVED BY
CONDITIONS OF APPROVAL, IF ANY:

TITLE

DATE

0-4- USGS
1- NSW
1- SOSD
1- RRY

JUL 18 1969

H. L. BECKMAN

*See Instructions on Reverse Side