

## INCLINATION REPORT

CHAMBERS & KENNEDY  
607 Midland National Bank Building  
Midland, Texas 79701

RECEIVED

JUL 18 1969


CHAMPLIN STATE Well No. 1  
S/E 1/4, S/W 1/4,  
Section 4, T-8-S, R-33-E,  
Chaves County, New Mexico

CHAMBERS & KENNEDY


## RECORD OF INCLINATION

<u>Depth (feet)</u>	<u>Angle of Inclination (degrees)</u>	<u>Displacement (feet)</u>	<u>Accumulative Displacement (feet)</u>
365	1/2	3.18	3.18
865	1/2	8.75	11.93
1,348	3/4	6.33	18.26
1,840	3/4	6.44	24.70
2,260	3/4	5.50	30.20
2,590	1	5.77	35.97
3,047	3/4	5.99	41.96
3,510	1	8.10	50.06
3,984	1	8.29	58.35
4,150	3/4	2.17	60.52
4,438	1	5.04	65.56

I hereby certify that I have personal knowledge of the data and facts placed on this report,  
and that such information given above is true and complete.

  
VERNA DRILLING COMPANY  
P. O. Box 1000  
Levelland, Texas 79336

Sworn and Subscribed before me, this the 14th day of July, 1969.

  
Notary Public in and for  
Hockley County, Texas