

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEYSUBMIT IN TRIPLY  
(Other instructions  
verse side)Form approved.  
Budget Bureau No. 42-11424.

5. LEASE DESIGNATION AND SERIAL NO.

NM 0109856

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

BAM FEDERAL

9. WELL NO.

1

10. FIELD AND POOL, OR WILDCAT

WILDCAT

11. SEC., T., R., M., OR BLK. AND  
SURVEY OR AREA

SEC. 21-14S-30E

12. COUNTY OR PARISH

CHAVES

13. STATE

NEW MEXICO

## SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.  
Use "APPLICATION FOR PERMIT—" for such proposals.)1. OIL WELL ☐ GAS WELL ☐ OTHER DRY HOLE

2. NAME OF OPERATOR

JACK L. MCCLELLAN

3. ADDRESS OF OPERATOR

P. O. Box 848, ROSWELL, NEW MEXICO, 88201

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.\*  
See also space 17 below.)  
At surface

660' FS &amp; WL

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

3857' G. L.

## 16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

## NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON\*

CHANGE PLANS

## SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT\*

(NOTE: Report results of multiple completion on Well  
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

PURSUANT TO VERBAL INSTRUCTIONS FROM MR. KNAUF, GIVEN ON JULY 8, 1970, THIS WELL WAS PLUGGED AND ABANDONED ON JULY 9, 1970, AS FOLLOWS: LOADED HOLE WITH 30 BARRELS WATER, PUMPED 50 SACKS CEMENT (550') AND DISPLACED WITH 22 BARRELS WATER, PLACING CEMENT PLUG AT T. D. A 10 SACK PLUG WAS PLACED IN THE ANNULUS BETWEEN THE 8-5/8" AND 4 1/2" CASING. AND THE 4 1/2" CASING. A DRY HOLE MARKER HAS BEEN PLACED IN THE 4 1/2" CASING. THIS WORK WAS PERFORMED BY DENTON OIL WELL CEMENTING COMPANY.

THIS WELL WAS INITIALLY FRACED WITH 16,000 GALS. LEASE CRUDE. ONLY ABOUT 6,000 GALS. WAS RECOVERED, LEAVING 10,000 GALS. LOAD OIL NOT RECOVERED.

THE LOCATION WILL BE CLEANED AND LEVELED ON JULY 10, 1970.

JUL 10 1970

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE

OPERATOR

DATE

JULY 9, 1970

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

APPROVED

AUG 18 1970

R. L. BEEKMAN

\*See Instructions on Reverse Side

RECEIVED

AUG 1970

ARTESIA, CALIF.

RECEIVED

AUG 19 1970

D. C. D.  
ARTESIA, CALIF.