

N. M. O. C.
UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN TRIPLICATE
(Other instructions on
reverse side)

Form approved.
Budget Bureau No. 42-R1424.

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>		5. LEASE DESIGNATION AND SERIAL NO. <div style="text-align: center;">NM-3286-A</div>	
2. NAME OF OPERATOR <div style="text-align: center;">McGrath & Smith, Inc.</div>		6. IF INDIAN, ALLOTTEE OR TRIBE NAME <div style="text-align: center;">-----</div>	
3. ADDRESS OF OPERATOR <div style="text-align: center;">418 Building of the Southwest, Midland, Texas 79701</div>		7. UNIT AGREEMENT NAME <div style="text-align: center;">-----</div>	
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface <div style="text-align: center;">1980 FNL & 1980 FEL</div>		8. FARM OR LEASE NAME <div style="text-align: center;">Sauer Federal</div>	
14. PERMIT NO.		9. WELL NO. <div style="text-align: center;">1</div>	
15. ELEVATIONS (Show whether DF, RT, GR, etc.) <div style="text-align: center;">GL 3986 KB 3997</div>		10. FIELD AND POOL, OR WILDCAT <div style="text-align: center;">Wildcat</div>	
		11. SEC., T., R., M., OR BLK. AND SURVEY OR ABBA <div style="text-align: center;">Sec. 23, T12S, R30E</div>	
		12. COUNTY OR PARISH <div style="text-align: center;">Chaves</div>	
		13. STATE <div style="text-align: center;">N.M.</div>	

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF <input type="checkbox"/>	PULL OR ALTER CASING <input type="checkbox"/>
FRACTURE TREAT <input type="checkbox"/>	MULTIPLE COMPLETE <input type="checkbox"/>
SHOOT OR ACIDIZE <input type="checkbox"/>	ABANDON* <input type="checkbox"/>
REPAIR WELL <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
(Other) <input type="checkbox"/>	

SUBSEQUENT REPORT OF:

WATER SHUT-OFF <input checked="" type="checkbox"/>	REPAIRING WELL <input type="checkbox"/>
FRACTURE TREATMENT <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
SHOOTING OR ACIDIZING <input type="checkbox"/>	ABANDONMENT* <input checked="" type="checkbox"/>
(Other) <input type="checkbox"/>	

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.) *

Spudded 8-6-70. Drld. 11" hole to 354'. Cmtd. 8 5/8-20# csg. at 353 with 175 sx. Circ. cmt. WOC 18 hrs. Tested 8 5/8 to 350 psi - O.K. Drld. 7 7/8 hole to TD 2905'. Cored Queen from 2282'-2310'. No shows. Ran GR-BHC Acoustilog, MLL, LL. Reached TD 8-10-70. P & A as follows: Spotted cement plugs as follows: 35sx. from 2250-2350', 35 sx. from 1370-1470', 35 sx. from 300-400, 10 sx. top of 8 5/8 from 0-20. Job complete at 9:00 pm, 8-11-70. Hole between plugs was filled with drlg. mud. No shows of oil or gas were found in this well. Used Class H neat cement. Dry hole marker was installed. Core was not analyzed - no shows - no porosity.

RECEIVED
AUG 13 1970
U.S. GEOLOGICAL SURVEY
ALBUQUERQUE, N.M.

18. I hereby certify that the foregoing is true and correct

SIGNED R. L. Beekman TITLE Sup't. DATE 8-13-70

(This space for Federal or State office use)

APPROVED BY R. L. Beekman TITLE Sup't. DATE 8-13-70

CONDITIONS OF APPROVAL, IF ANY:

APPROVED
FEB 13 1971
R. L. BEEKMAN
ACTING DISTRICT ENGINEER

*See Instructions on Reverse Side

RECEIVED

FEB 22 1971

OIL CONSERVATION COMM.
WASHINGTON, D.C.

RECEIVED

FEB 19 1971

D.C.C.
ASTORIA, OFFICE