

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN TRIPLICATE
(Other instructions on
reverse side)

Form approved.

Geological Survey

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/> DRY HOLE		5. LEASE DESIGNATION AND SERIAL NO. NM S255	
2. NAME OF OPERATOR OCCIDENTAL PETROLEUM CORPORATION		6. IF INDIAN, ALLOTTEE OR TRIBE NAME	
3. ADDRESS OF OPERATOR 306 WALL TOWERS EAST, MIDLAND, TEXAS 79701		7. UNIT AGREEMENT NAME	
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface 660' FNL & 660' FWL		8. FARM OR LEASE NAME GOVERNMENT 15	
14. PERMIT NO.		9. WELL NO. 1	
15. ELEVATIONS (Show whether DF, RT, GR, etc.) 3881' GL 3882' DF		10. FIELD AND POOL, OR WILDCAT WILDCAT	
		11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA SEC. 15-T14S-R30E	
		12. COUNTY OR PARISH CHAVES	
		13. STATE NEW MEXICO	

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
TEST WATER SHUT-OFF <input type="checkbox"/>	PULL OR ALTER CASING <input type="checkbox"/>	WATER SHUT-OFF <input type="checkbox"/>	REPAIRING WELL <input type="checkbox"/>
FRACTURE TREAT <input type="checkbox"/>	MULTIPLE COMPLETE <input type="checkbox"/>	FRACTURE TREATMENT <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
SHOOT OR ACIDIZE <input type="checkbox"/>	ABANDON* <input type="checkbox"/>	SHOOTING OR ACIDIZING <input type="checkbox"/>	ABANDONMENT* <input checked="" type="checkbox"/>
REPAIR WELL <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	(Other) <input type="checkbox"/>	

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

THIS TEST WAS PLUGGED & ABANDONED 5/2/71 THRU 5/4/71, AS FOLLOWS:

100' CEMENT PLUG SET 2125' TO 2225' (TOTAL DEPTH 2225')
 100' " " " 1315' TO 1450' (BASE OF SALT 1365')
 200 SACKS OF CEMENT FROM 400' TO 1200' (WATER SHUT OFF. TESTED WATER 12 HOURS. NO WATER)
 20' PLUG AT SURFACE.

RECEIVED
MAY - 5 1971
U. S. GEOLOGICAL SURVEY
ARTESIA NEW MEXICO

18. I hereby certify that the foregoing is true and correct

SIGNED J. M. C. C. TITLE AGENT DATE 5/4/71

(This space for Federal or State office use)

APPROVED BY J. M. C. C. TITLE AGENT DATE 5/4/71

CONDITIONS OF APPROVAL, IF ANY:

*See Instructions on Reverse Side

RECEIVED

FEB 27 1974

O. C. C.
ARTESIA, OFFICE