

SUNDRY NOTICES AND REPORTS ON WELLS C. G. CORY

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use "APPLICATION FOR PERMIT" for such proposals.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/> DRY HOLE <input checked="" type="checkbox"/> RECEIVED		6. IF INDIAN, ALIQUOT OR TRIBE NAME	
2. NAME OF OPERATOR JACK L. McCLELLAN		8. FARM OR LEASE NAME "JL" FEDERAL	
3. ADDRESS OF OPERATOR Box 848, ROSWELL, NEW MEXICO 88201		9. WELL NO. 1	
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.) At surface ARTESIA, OFFICE		10. FIELD AND POOL, OR WILDCAT DOUBLE L QUEEN	
14. PERMIT NO.		11. SEC., T., R., M., OR BLM. AND SURVEY OR AREA SEC. 30-T14S-R30E	
15. ELEVATIONS (Show whether DF, RT, GR, etc.) 3845 G.L.		12. COUNTY OR PARISH CHAVES	
		13. STATE N. M.	

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
TEST WATER SHUT-OFF <input type="checkbox"/>	PULL OR ALTER CASING <input type="checkbox"/>	WATER SHUT-OFF <input type="checkbox"/>	REPAIRING WELL <input type="checkbox"/>
FRACTURE TREAT <input type="checkbox"/>	MULTIPLE COMPLETE <input type="checkbox"/>	FRACTURE TREATMENT <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
SHOOT OR ACIDIZE <input type="checkbox"/>	ABANDON* <input type="checkbox"/>	SHOOTING OR ACIDIZING <input type="checkbox"/>	ABANDONMENT* <input checked="" type="checkbox"/>
REPAIR WELL <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	(Other) <input type="checkbox"/>	

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.) *

ON 7/05/71, TEST RESULTED IN NO FLUID IN QUEEN.

PLUGGED AND ABANDONED AS FOLLOWS:

- 100' PLUG AT T.D. OF 1992'
- 100' " " 1100' (BASE OF SALT)
- 100' " " 400' (TOP OF SALT)
- 20' " " SURFACE

SET MARKER. WILL CLEAN LOCATION AND FILL PITS.

RECEIVED
JUL 29 1971
U. S. GEOLOGICAL SURVEY
ARTESIA, NEW MEXICO

18. I hereby certify that the foregoing is true and correct

SIGNED Jack L. McClellan TITLE Operator DATE 7/23/71

(This space for Federal or State office use)

APPROVED BY H. L. BEEKMAN TITLE Acting District Engineer DATE SEP 18 1972

SEP 18 1972
H. L. BEEKMAN
ACTING DISTRICT ENGINEER

*See Instructions on Reverse Side