

# NM OIL CONS. COMMISSION

Drawer DD

Artesia, NM 88210

Form 9-331  
Dec. 1973

Form Approved.  
Budget Bureau No. 42-R1424

UNITED STATES

DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

RECEIVED

FEB 28 10 05 AM '84

## SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)

1. oil well ☐ gas well ☒ other ☐

2. NAME OF OPERATOR

McClellan Oil Corporation

3. ADDRESS OF OPERATOR

P. O. Drawer 730, Roswell, NM 88202

4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)

AT SURFACE: 1980' FSL & 660' FEL

AT TOP PROD. INTERVAL:

AT TOTAL DEPTH:

16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

REQUEST FOR APPROVAL TO:

SUBSEQUENT REPORT OF:

TEST WATER SHUT-OFF ☐

FRACTURE TREAT ☐

SHOOT OR ACIDIZE ☐

REPAIR WELL ☐

PULL OR ALTER CASING ☐

MULTIPLE COMPLETE ☐

CHANGE ZONES ☐

ABANDON ☐

(other) Plug and Abandon

5. LEASE

NM-0554965

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Federal "I"

9. WELL NO.

1

10. FIELD OR WILDCAT NAME

Wildcat

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA

Sec. 8-T15S-R30E

12. COUNTY OR PARISH

Chaves

13. STATE

New Mexico

14. API NO.

30-005-20429

15. ELEVATIONS (SHOW DF, KDB, AND WD)

4012' GL

(NOTE: Report results of multiple completion or zone change on Form 9-330.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

Well has been plugged and abandoned as follows:

Pulled 1471' of 4 1/2" casing.

Set cement plug from 2070' - 2230' across present perforations.

Set cement plug from 1286' - 1520' in and out of 4-1/2" casing.

Set cement plug from 434' - 650' in and out of 8-5/8" casing.

20 sx cement plug at surface. Heavy mud between each plug.

Placed dry hole marker, clean, backfill pits and rip location and road.

Subsurface Safety Valve: Manu. and Type

Set @

Ft.

18. I hereby certify that the foregoing is true and correct

SIGNED Mark McClellan TITLE Geologist

DATE February 24, 1984

(This space for Federal or State office use)

APPROVED BY (C. W. CHESTER

CONDITIONS OF APPROVAL, IF ANY

TITLE

DATE

MAR 26 1984

\*See Instructions on Reverse Side

RECEIVED  
MAR 28 1984  
O. C. D.  
ARTESIA, OFFICE

RECEIVED  
APR 2 - 1984  
O. C. D.  
HOBBS OFFICE