

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN TRIPL.
(Other instructions on
reverse side)

E*
e-

Form approved.
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

NM 18508

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Luther-A

9. WELL NO.

1

10. FIELD AND POOL, OR WILDCAT

Lonesome San Andres

11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA

18, 8-S, 32-E

12. COUNTY OR PARISH 13. STATE

Chaves

New Mexico

1.

OIL WELL ☒ GAS WELL ☐ OTHER

2. NAME OF OPERATOR

Phillips Petroleum Company

3. ADDRESS OF OPERATOR

Room 711, Phillips Building, Odessa, Texas 79761

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*
See also space 17 below.)
At surface

(Unit N) 660' FS & 1980' FW lines

14. PERMIT NO.

15. ELEVATIONS (Show whether DE, RT, GR, etc.)

4395.2' Gr.

16.

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

PULL OR ALTER CASING

FRACTURE TREAT

MULTIPLE COMPLETION

SHOOT OR ACIDIZE

ABANDON*

REPAIR WELL

CHANGE PLANS

(Other)

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

X

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

2-18-76: MI Baber WS unit. Pld rods & pump. Spotted 200 sx Class H cmt at 4720'

2-19-87: Tagged top cmt at 4000', loaded hole w/mud laden brine.

2-20-76/2-21-76: Down 48 hrs, high wind.

2-22-76: Cut 8-5/8" csg at 1197', pulled and recovered 1197' of 8-5/8" OD 32# csg.
Ran 2-3/8" tbg to 1250', Baber spotted 50 sx cmt from 1250' to 1150'. Pld
tbg to 500', spotted 100 sx cmt of/500' to 350'. Spotted 10 sx cmt from 35'
to surface. Installed well marker. Well P&A.

18. I hereby certify that the foregoing is true and correct

SIGNED

W. J. Mueller

TITLE Engineering Advisor

DATE 2-24-76

(This space for Federal or State office use)

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

TITLE

APPROVED

JUL 12 1976

ARTHUR R. BROWN
DISTRICT ENGINEER

*See Instructions on Reverse Side

RECEIVED

JUL 2 1970

OIL CONSERVATION COMM.
DOBBS, N. M.