

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEYSUBMIT IN TRIPLICATE  
(Other instructions  
verse side)Form approved.  
Budget Bureau No. 42 R1424.  
5. LEASE DESIGNATION AND SERIAL NO.

NM 0199827-A

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

## SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.  
Use "APPLICATION FOR PERMIT" for such proposals.)

|   |  |   |  |
|---|--|---|--|
| 1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>  |  | 7. UNIT AGREEMENT NAME  |  |
| 2. NAME OF OPERATOR<br>Charles W. Hicks   |  | 8. FARM OR LEASE NAME<br>Amerada Federal  |  |
| 3. ADDRESS OF OPERATOR<br>1314 North Richardson, Roswell, New Mexico 88201  |  | 9. WELL NO.<br>1  |  |
| 4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*<br>See also space 17 below.)<br>At surface<br><br>610' FSL, 2310' FWL Section 5, T-15-S, R-30-E N.M.P.M. |  | 10. FIELD AND POOL, OR WILDCAT<br>Double L Extension                            |  |
| 14. PERMIT NO.  |  | 11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA<br>Section 5<br>T-15-S, R-30-E |  |
| 15. ELEVATIONS (Show whether DF, RT, GR, etc.)<br>3922' GR  |  | 12. COUNTY OR PARISH<br>Chaves  |  |
|   |  | 13. STATE<br>New Mexico   |  |

## 16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

## NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON\*

CHANGE PLANS

## SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT\*

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

1974

Oct. 7 Spud Well

Nov. 2 Ran 460' 8 5/8" 28 & 32# and cemented.  
Cement circulated.Nov. 4 Drilled out below casing and tested. No leaks.  
Tested OK

RECEIVED

NOV 14 1974

U. S. GEOLOGICAL SURVEY  
ARTESIA, NEW MEXICO

18. I hereby certify that the foregoing is true and correct

SIGNED

Charles W. Hicks

TITLE

Operator

DATE

Nov. 12, 1974

(This space for Federal or State office use)

APPROVED BY

[Signature]

TITLE

DISTRICT ENGINEER

DATE

NOV 27 1974

CONDITIONS OF APPROVAL, IF ANY:

\*See Instructions on Reverse Side