NMOCC COPY

Form approved. Budget Bureau No. 42-R1424. SUBMIT IN TRIPL UN. . . D STATES DEPARTMENT OF THE INTERIOR (Other instructions verse side) Form 9-331 (May 1963) 5. LEASE DESIGNATION AND SERIAL NO. NM 0558016 GEOLOGICAL SURVEY 6. IF INDIAN, ALLOTTEE OR TRIBE NAME SUNDRY NOTICES AND REPORTS ON WELLS (Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.

Use "APPLICATION FOR PERMIT" for such proposals.) 7. UNIT AGREEMENT NAME FEEL OIL WELL Dry Hole GAS WELL OTHER 8. FARM OR LEASE NAME 2. NAME OF OPERATOR Cedar Point McClellan Oil Corporation 9. WELL NO. 3. ADDRESS OF OPERATOR **%** | P. O. Box 848, Roswell, NM LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.)
At surface 10. FIELD AND POOL, OR WILDCAT Wildcat : 11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA 990' FWL & 660' FNL 21-T15S-R30E 12. COUNTY OR PARISH | 13. STATE 15. ELEVATIONS (Show whether DF, RT, GR, etc.) 14 PERMIT NO. Μ. Chaves 4041.4 G.L. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data 16. 5 17 SUBSEQUENT REPORT OF NOTICE OF INTENTION TO: REPAIRING WELL WATER SHUT-OFF PULL OR ALTER CASING TEST WATER SHUT-OFF ALTERING CASING FRACTURE TREATMENT MULTIPLE COMPLETE FRACTURE TREAT ABANDON MENT SHOOTING OR ACIDIZING ABANDON* SHOOT OR ACIDIZE (Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.) CHANGE PLANS REPAIR WELL 17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.) • Permission was given verbally 9/13/77 to P&A this test, which was subsequently plugged as follows on 9/30/77: 35 sx cement plug 3712-3812' (T. D.), 35 sx plug 2250-2750' (Queen), 35 sx plug 650-750' (Base of 8-5/8" casing) and 20' plug @ surface. Heavy mud was pumped between all plugs. Will set dry hole marker and restore surface. RECEIVED OCT 27 1977 U.S. GEULUGICAL SURVEY ARTESIA, NEW MEXICO that the foregoing is true and correct 18. I hereby certi 10/26/77 Operator DATE TITLE

TITLE ACTING DISTRICT ENGINEER

DATE MAR 2 1 1978

SIGNEL

(This space for

APPROVED BY CONDITIONS

Federal

APPROVAL, IF ANY: