

M-G-F DRILLING Co., INC.

7TH FLOOR, VAUGHN BUILDING

MIDLAND, TEXAS 79701

915 - 684-7173

INCLINATION REPORT

OPERATOR:

Britton Management Corporation
312 North Big Spring
Midland, Texas 79701


LOCATION:

No. 2 Hannifin
1980' FN & WL of Section 31,
T-9-S, R-30-E, Chaves County,
New Mexico.


Depth Feet	Inclination Degrees	Depth Feet	Inclination Degrees	Depth Feet	Inclination Degrees	Depth Feet	Inclination Degrees
400	1 3/4	5400	1	9350 TD	1/2		
821	1	5827	1				
1060	1	6050	1				
1553	1 1/4	6160	1				
1924	1	6649	1				
2200	1	7047	1/2				
2670	1	7240	1/2				
2854	1 1/4	7728	1				
3270	1 1/2	7998	1				
3715	1 1/2	8263	1 1/2				
3988	1 1/2	8518	1 1/2				
4232	1 1/4	8820	1				
4479	3/4	9046	1				
4941	1	9292	1/2				

STATE OF TEXAS
COUNTY OF MIDLAND

The undersigned states that he has knowledge of the facts and matter herein set forth and that the same are true and correct.


L. E. Grimes, Vice President, Manager

SUBSCRIBED AND SWORN TO BEFORE ME this the 9 day of July, 19 76.


Notary Public in and for Midland County
Texas.

My Commission Expires: June 1, 1977



RECEIVED

NOV 10 1976

OIL CONSERVATION COMM.
HOBBS, N. M.