

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEYSUBMIT IN TRIPPLICATE  
(Other instructions  
verse side)Form approved.  
Budget Bureau No. 42-R1424.

## SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.  
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <u>Wildcat Test</u>		5. LEASE DESIGNATION AND SERIAL NO. <u>NM 11963-A</u>
2. NAME OF OPERATOR <u>Cleary Petroleum Corporation</u>		6. IF INDIAN, ALLEGOTTE OR TRIBE NAME ---
3. ADDRESS OF OPERATOR <u>P. O. Drawer 2358, Midland, Texas 79702</u>		7. UNIT AGREEMENT NAME ---
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface  <u>660' FSL &amp; 660' FWL</u>		8. FARM OR LEASE NAME <u>Federal "15"</u>
14. PERMIT NO. <u>Approved 12-20-76</u>		9. WELL NO. <u>4</u>
15. ELEVATIONS (Show whether DF, RT, GR, etc.) <u>4235' GL</u>		10. FIELD AND POOL, OR WILDCAT <u>Wildcat</u>
		11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA <u>Sec. 3, T-7-S, R-36-E</u>
		12. COUNTY OR PARISH 13. STATE <u>Chaves</u> <u>N. M.</u>

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data:

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF	
TEST WATER SHUT-OFF <input type="checkbox"/>	PULL OR ALTER CASING <input type="checkbox"/>	WATER SHUT-OFF <input type="checkbox"/>	REPAIRING WELL <input type="checkbox"/>
FRACTURE TREAT <input type="checkbox"/>	MULTIPLE COMPLETION <input type="checkbox"/>	FRACTURE TREATMENT <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
SHOOT OR ACIDIZE <input type="checkbox"/>	ABANDON* <input checked="" type="checkbox"/>	SHOOTING OR ACIDIZING <input type="checkbox"/>	ABANDONMENT* <input type="checkbox"/>
REPAIR WELL <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	(Other) <input type="checkbox"/>	(Other) <input type="checkbox"/>

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting and proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

Cleary Petroleum Corporation proposes to plug and abandon the above well with the following procedure as object zones were not productive:

100' plug (30 sx of Class "H") @ 2500 - 2600'  
100' plug (30 sx of Class "H") @ 1106 - 1206'  
20' plug (Class "H") in surface.

8 5/8" surface csg. will remain intact as reported on previous Sundry Notice.

This report is filed as a matter of record, verbal approval was received from R. L. Beekman on 2-8-77.

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE District Production Manager

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

RECEIVED

MAR 31 1977

U.S. GEOLOGICAL SURVEY  
ARTESIA, NEW MEXICO

MAR 31 1977

R. L. BECKMAN  
ACTING DISTRICT ENGINEER

\*See Instructions on Reverse Side

RECEIVED

APR 4 1977

OIL COMPANY OF CALIF.  
HUNTER, H. L.

RECEIVED

MAR 31 1977

O. C. C.  
ARTESIA, OFFICE