

Form 9-331  
(May 1963)UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEYSUBMIT IN TRIPLICATE\*  
(Other instructions on reverse side)Form approved.  
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

NM-11329

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Grynberg Federal

9. WELL NO.

2

10. FIELD AND POOL, OR WILDCAT

Wildcat, San Andres

11. SEC., T., R., M., OR BLK. AND  
SURVEY OR AREA

Section 14, T.8S., R.31E.

12. COUNTY OR PARISH

Chaves

13. STATE

New Mexico

## SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.  
Use "APPLICATION FOR PERMIT—" for such proposals.)

1.

OIL  
WELL☐GAS  
WELL☐

OTHER

DRY

2. NAME OF OPERATOR

SUNDANCE OIL COMPANY

3. ADDRESS OF OPERATOR

Suite 510, 1776 Lincoln St., Denver, CO 80203

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.\*

See also space below.)  
At surface

660' FSL, 660' FEL, Unit F

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

4278.1' GL

16.

## Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

## NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

☐  
☐  
☐  
☐

PULL OR ALTER CASING

☐  
☐  
☐  
☐

FRACTURE TREAT

MULTIPLE COMPLETE

SHOOT OR ACIDIZE

ABANDON\*

REPAIR WELL

CHANGE PLANS

(Other)

## SUBSEQUENT REPORT OF:

WATER SHUT-OFF

☐  
☐  
☐

REPAIRING WELL

☐  
☐  
☐  
☐

FRACTURE TREATMENT

ALTERING CASING

SHOOTING OR ACIDIZING

ABANDONMENT\*

XXXX

(Other)

(NOTE: Report results of multiple completion on Well  
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

Verbal permission to plug well was received on 5/10/77. Plugged well as follows:

35 sx cement at 3250' (Top of San Andres)

45 sx cement at 1540' (Top of salt to base of surface pipe)

20 sx cement at top of 8 5/8" surface casing

All pits were filled &amp; location cleaned of all trash and junk. Road was left in place pending possible future re-entry for deeper test. Landowner using road to gain access to livestock.

18. I hereby certify that the foregoing is true and correct

SIGNED

Richard O. Dinit

TITLE Vice President, Production

DATE 2/18/80

(This space for Federal or State office use)

APPROVED BY

Richard O. Dinit

TITLE

ACTING DISTRICT ENGINEER

DATE

FEB 28 1980

CONDITIONS OF APPROVAL, IF ANY:

\*See Instructions on Reverse Side

Main Change

RECEIVED

FEB 29 1980

O. C. D.  
ARTESIA, OFFICE

RECEIVED

MAR 9 1980

OR CONSERVATION DIV