

Form 9-331
(May 1963)UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYSUBMIT IN TRIPLICATE 3*
(Other instructions on reverse side)Form approved.
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

NM-11329

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Grynberg Federal

9. WELL NO.

1

10. FIELD AND POOL, OR WILDCAT

Wildcat, San Andres

11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA

Section 11, T.8S., R.31E.

12. COUNTY OR PARISH

Chaves

13. STATE

New Mexico

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1.

OIL WELL ☐ GAS WELL ☐ OTHER ☐

DRY

2. NAME OF OPERATOR

SUNDANCE OIL COMPANY

3. ADDRESS OF OPERATOR

Suite 510, 1776 Lincoln St., Denver, CO 80203

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*
See also space 17 below.)
At surface

660' FNL, 1980' FEL, Unit B

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

4387' GL, 4397' KB

16.

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

☐
☐
☐
☐

PULL OR ALTER CASING

☐
☐
☐
☐

FRACTURE TREAT

MULTIPLE COMPLETE

SHOOT OR ACIDIZE

ABANDON*

REPAIR WELL

CHANGE PLANS

(Other)

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

☐
☐
☐
☐

REPAIRING WELL

☐
☐
☐
☐

FRACTURE TREATMENT

ALTERING CASING

SHOOTING OR ACIDIZING

ABANDONMENT*

(Other)

(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Verbal permission to plug was received 5/21/77. Well was plugged as follows:

35 sx cement at 3246'

45 sx cement at 1588' (top of Salt into 8 5/8" casing at 1561')

20 sx at surface

Reserve pits were filled & location cleaned of all junk. Road was left in place pending possible future re-entry for deeper test. Also, landowner uses road to gain access to livestock.

18. I hereby certify that the foregoing is true and correct

SIGNED

Richard O. Dimit

TITLE Vice President, Production

DATE 2/18/80

(This space for Federal or State office use)

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

TITLE

ACTING DISTRICT ENGINEER

DATE

FEB 28 1980

RECEIVED

FEB 29 1980

C. C. D.

APPROVAL OFFICE

RECEIVED

MAR 3 1980

CH CONSERVATION DIV