

Form 9-351  
May 1963

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

SUBMIT IN TRIPPLICATE\*  
(Other instructions on reverse side)

Form approved.  
Budget Bureau No. 42 R1424  
LEASE DESIGNATION AND SERIAL NO.

NM-0354427-A

INDIAN ALLOTTEE OR TRIBE NAME

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.  
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. UNIT OR WELL NAME
2. NAME OF OPERATOR Harvey E. Yates Company, Inc.	8. FARM OR LEASE NAME Amoco Federal
3. ADDRESS OF OPERATOR Suite 1000 Security National Bank Bldg., Roswell, N. M.	9. WELL NO. 1
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.) At surface 1980' FNL & 660' FEL	10. FIELD AND POOL OR WILDCAT Cato-San Andres
14. PERMIT NO.	11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec. 1, T-8S, R-30E
15. ELEVATIONS (Show whether DF, RT, GR, etc.) 4215.2' GI	12. COUNTY OR PARISH Chaves
	13. STATE N. M.

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF <input type="checkbox"/>	PULL OR ALTER CASING <input type="checkbox"/>
FRACTURE TREAT <input type="checkbox"/>	MULTIPLE COMPLETION <input type="checkbox"/>
SHOOT OR ACIDIZE <input type="checkbox"/>	ABANDON* <input type="checkbox"/>
REPAIR WELL <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
(Other) <input type="checkbox"/>	

SUBSEQUENT REPORT OF:

WATER SHUT-OFF <input type="checkbox"/>	REPAIRING WELL <input type="checkbox"/>
FRACTURE TREATMENT <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
SHOOTING OR ACIDIZING <input type="checkbox"/>	ABANDONMENT* <input type="checkbox"/>
(Other) <u>Run production casing</u> <input checked="" type="checkbox"/>	

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.) \*

6-5-77 Ran 96 Joints (3790') 4 1/2" OD. 9.5-8 rd. ST&C casing. Set at 3800' and cemented with 275 S. Class C 50-50 Poz 2% Gel and 6# Salt per sack. WOC 36 Hrs.  
Pressured up on casing to 1500#. OK.

Deviation survey included

RECEIVED

JUN 21 1977

U.S. GEOLOGICAL SURVEY  
ARTESIA, NEW MEXICO

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE Vice President

DATE June 6, 1977

(This space for Federal or State office use)

APPROVED BY

TITLE ACTING DISTRICT ENGINEER

DATE JUN 22 1977

CONDITIONS OF APPROVAL, IF ANY:

D.C.C.  
ANTENNA OFFICE

JUN 23 1977

RECEIVED