B 18 CM 40AS MARKININ P. O. DOM 1080 HOBBS, NEW MEXICO 88240

Form 9-331 Dec. 1973

Dec. 1973 Form Approved. Budget Bureau No. 42-R1424 UNITED STATES 5. LEASE DEPARTMENT OF THE INTERIOR NM 13999A **GEOLOGICAL SURVEY** 6. IF INDIAN, ALLOTTEE OR TRIBE NAME SUNDRY NOTICES AND REPORTS ON WELLS 7. UNIT AGREEMENT NAME (Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.) 8. FARM OR LEASE NAME gas weii 🖾 Phillips Federal well other 9. WELL NO. 2. NAME OF OPERATOR 33 El Ran, Inc. 10. FIELD OR WILDCAT NAME 3. ADDRESS OF OPERATOR Chaveroo SH P.O. Box 911, Lubbock, TX 79408 11. SEC., T., R., M., OR BLK. AND SURVEY OR 4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 AREA below.) Section 13, T8S, R32E AT SURFACE:Unit Letter X, 1980' FSL&1980' FEL 12. COUNTY OR PARISH 13. STATE AT TOP PROD. INTERVAL: AT TOTAL DEPTH: Chaves · NM 4360' 14. API NO. 16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, <u> 3D-005-</u> 20711 REPORT, OR OTHER DATA 15. ELEVATIONS (SHOW DF, KDB, AND WD) 4433' GL REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF: TEST WATER SHUT-OFF FRACTURE TREAT SHOOT OR ACIDIZE REPAIR WELL (NOTE: Report results of multiple completion or zone PULL OR ALTER CASING MULTIPLE COMPLETE change on Form 9-330.) CHANGE ZONES ABANDON\* (other) 17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\* The surface reclamation is complete and ready for inspection. We are requesting approval of FINAL ABANDONMENT. Subsurface Safety Valve: Manu. and Type \_\_\_ Set @ 18. I hereby certify that the foregoing is true and correct TITLE Production Analyst DATE 4/8/93 (This space for Federal or State office use) APPROVED BY CONDITIONS OF APPROVAL, IF