

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen a well or to develop a reservoir. Use Form 9-331-C for such proposals.)

RECEIVED  
DEC 23 1980

1. oil well ☒ gas well ☐ other ☐

2. NAME OF OPERATOR  
El Ran, Inc.

U. S. GEOLOGICAL SURVEY  
HOBBS, NEW MEXICO

3. ADDRESS OF OPERATOR  
P. O. Box 911, Lubbock, Texas 79408

4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)  
AT SURFACE: 990' FWL & 660' FSL  
AT TOP PROD. INTERVAL:  
AT TOTAL DEPTH:

16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

REQUEST FOR APPROVAL TO:

SUBSEQUENT REPORT OF:

TEST WATER SHUT-OFF ☐  
FRACTURE TREAT ☐  
SHOOT OR ACIDIZE ☐  
REPAIR WELL ☐  
PULL OR ALTER CASING ☐  
MULTIPLE COMPLETE ☐  
CHANGE ZONES ☐  
ABANDON\* ☐

☐  
☐  
☐  
☐  
☐  
☐  
☐  
☐

(other) Casing Program

(NOTE: Report results of multiple completion or zone change on Form 9-330.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

8 5/8" 23# casing was set at 1698' and cemented with 550 sacks.  
Casing was tested after 18 hours to 1000# with no leaks  
sacks circulated.

4 1/2" 10.5# casing was set at 4413' and cemented with 50/50 POZ.

ACCEPTED FOR RECORD

DEC 29 1980

U.S. GEOLOGICAL SURVEY  
RECEIVED

Subsurface Safety Valve: Manu. and Type

18. I hereby certify that the foregoing is true and correct

SIGNED Robert R. Hanks TITLE Vice-President

DATE December 22 1980

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

COPY