

**UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY**

**SUNDRY NOTICES AND REPORTS ON WELLS**

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)

1. oil ☒ gas ☐  
well well other

2. NAME OF OPERATOR  
SUNDANCE OIL COMPANY

3. ADDRESS OF OPERATOR  
#510, 1776 Lincoln St., Denver, CO 80203

4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)  
AT SURFACE: 1655' FNL, 1655' FWL, Unit F  
AT TOP PROD. INTERVAL:  
AT TOTAL DEPTH: Same

16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

REQUEST FOR APPROVAL TO:

SUBSEQUENT REPORT OF:

TEST WATER SHUT-OFF ☐  
FRACTURE TREAT ☐  
SHOOT OR ACIDIZE ☐  
REPAIR WELL ☐  
PULL OR ALTER CASING ☐  
MULTIPLE COMPLETE ☐  
CHANGE ZONES ☐  
ABANDON\* ☐  
(other) SET SURFACE CASING

☐  
☐  
☐  
☐  
☐  
☐  
☐  
☐  
☐

5. LEASE  
NM-15678

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME  
Ingram Federal

9. WELL NO.  
14

10. FIELD OR WILDCAT NAME  
Tom-Tom, San Andres

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA  
SE NW Section 5, T.8S., R.31E.

12. COUNTY OR PARISH 13. STATE  
Chaves New Mexico

14. API NO.

15. ELEVATIONS (SHOW DF, KDB, AND WD)  
4242' GL, 4254' KB

(NOTE: Report results of multiple completion or zone change on Form 9-330.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

Spudded 12 1/4" surface hole at 12:45 p.m. 8/19/80. Drilled to 1376'. Ran 35 jts. 8 5/8", 24# surface casing. Set at 1363'. Cemented with 250 sx Class C, 3% lowdense and 200 sx Class C, 2% CaCl<sub>2</sub>. Plug down at 11:15 a.m. 8/20/80. Circulated 35 sx cement. Pressured up to 1000#, okay. WOC.

**RECEIVED**

AUG 27 1980

U.S. GEOLOGICAL SURVEY  
ARTESIA, NEW MEXICO

Subsurface Safety Valve: Manu. and Type

Set @ \_\_\_\_\_ Ft.

18. I hereby certify that the foregoing is true and correct

SIGNED Richard O. Dimit TITLE V-P, Production DATE August 25, 1980

(This space for Federal or State office use)

APPROVED BY \_\_\_\_\_  
CONDITIONS OF APPROVAL, IF ANY:

TITLE \_\_\_\_\_ DATE \_\_\_\_\_

**ACCEPTED FOR RECORD**

AUG 29 1980

U.S. GEOLOGICAL SURVEY  
ROSWELL, NEW MEXICO