

Form 9-331  
Dec. 1973Form Approved.  
Budget Bureau No. 42-R1424UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

## SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)

1. oil well ☒ gas well ☐ other ☐
2. NAME OF OPERATOR  
SUNDANCE OIL COMPANY
3. ADDRESS OF OPERATOR  
#910, 1776 Lincoln St., Denver, CO 80203
4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)  
AT SURFACE: 2304' FSL, 1655' FWL, Unit K  
AT TOP PROD. INTERVAL:  
AT TOTAL DEPTH: Same
16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

## REQUEST FOR APPROVAL TO:

- TEST WATER SHUT-OFF ☐
- FRACTURE TREAT ☐
- SHOOT OR ACIDIZE ☐
- REPAIR WELL ☐
- PULL OR ALTER CASING ☐
- MULTIPLE COMPLETE ☐
- CHANGE ZONES ☐
- ABANDON\* ☐
- (other) RAN SURFACE CASING ☐

## SUBSEQUENT REPORT OF:

- ☐
- ☐
- ☐
- ☐
- ☐
- ☐
- ☐
- ☐
- ☐

RECEIVED

SEP 11 1980

U.S. GEOLOGICAL SURVEY  
ARTESIA, NEW MEXICO

5. LEASE  
NM-15678
6. IF INDIAN, ALLOTTEE OR TRIBE NAME
7. UNIT AGREEMENT NAME
8. FARM OR LEASE NAME  
Ingram Federal
9. WELL NO.  
15
10. FIELD OR WILDCAT NAME  
Tom-Tom, San Andres
11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA  
NE SW Section 5, T.8S, R.31E
12. COUNTY OR PARISH  
Chaves
13. STATE  
New Mexico
14. API NO.
15. ELEVATIONS (SHOW DF, KDB, AND WD)  
4232' GL, 4244' KB

NOTE: Report results of multiple completion or zone change on Form 9-330.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

Spudded 12 1/4" surface hole at 12 midnight 8-29-80. Drilled to 1428'.  
Ran 36 jts. 8 5/8", 24# surface casing. Set at 1408'. Cemented w/250 sx Class C, 3% Econolite and 200 sx Class C, 2% CaCl<sub>2</sub>. Plug down at 10:30 p.m. 8-31-80.  
Circulated 41 sx. Pressured up to 1500 #, okay. WOC.

Subsurface Safety Valve: Manu. and Type \_\_\_\_\_ Set @ \_\_\_\_\_ Ft.

18. I hereby certify that the foregoing is true and correct

SIGNED Richard O. Dimit TITLE V-P, Production DATE 9-8-80

APPROVED BY \_\_\_\_\_  
CONDITIONS OF APPROVAL, IF ANY:

(This space for Federal or State office use)

ACCEPTED FOR RECORD

SEP 15 1980

U.S. GEOLOGICAL SURVEY  
ROSWELL, NEW MEXICO

O. C. D.  
ARTESIA, OFFICE

SEP 22 1980

RECEIVED

RECEIVED

SEP 22 1980

SEP 22 1980