Form 9-331 Dec. 1973

| Form A | pproved | i. | | |
|--------|---------|-----|------|-----|
| Budget | Bureau | No. | 42-R | 142 |

| UNITED STATES | E LEACE |
|---|--|
| DEPARTMENT OF THE INTERIOR | 5. LEASE |
| GEOLOGICAL SURVEY | NM-046153-A 6. IF INDIAN, ALLOTTEE OR TRIBE NAME |
| | - THOMAN, ALEOTTEE OR TRIBE NAME |
| SUNDRY NOTICES AND REPORTS ON WELLS | 7. UNIT AGREEMENT NAME |
| (Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9–331–C for such proposals.) | - 1 (1 を) - 1 (1 を) |
| reservoir, Use Form 9–331–C for such proposals.) | 8. FARM OR LEASE NAME |
| 1. oil gas | Western Reserves 34 Federa |
| Well Other | 9. WELL NO. |
| 2. NAME OF OPERATOR MORANCO | 4 3 5 3 3 |
| 3. ADDRESS OF OPERATOR | 10. FIELD OR WILDCAT NAME |
| D O B 1000 W 11 | Tom-Tom (San Andres) |
| 4. LOCATION OF WELL (REPORT LOCATION CLEARLY C | 11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA |
| 4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.) 990 FWL & 530 FNL, Sec. 34, | Sec. 34, T-7-S, R-31-E |
| AT SURFACE: $T-7-S$, $R-31-E$ | 12. COUNTY OR PARISH 13. STATE |
| AT TOP PROD. INTERVAL: 3900 + | Chaves NM |
| AT TOTAL DEPTH: 4130 '± | 14. API NO. |
| 16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, | |
| REPORT, OR OTHER DATA | 15. ELEVATIONS (SHOW DF, KDB, AND WD) |
| REQUEST FOR APPROVAL TO: SUBSECUENT REPORT OF | 4328' KB 3 3 3 3 5 5 |
| REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF: | |
| FRACTURE TREAT | 그는 그는 그는 항상폭력 그 등 영광화를 하는 것 |
| SHOOT OR ACIDIZE | 그 그 그는 그는 항통과본 이 왕이들과 |
| REPAIR WELL | (NOTE: Report results of multiple completion or zone |
| MULTIPLE COMPLETE | change on Form 9–330.) |
| CHANGE ZONES | |
| ABANDON* | annisous de la company de la c |
| (other) Surface Casing & Cement Report | |
| 17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (C) | |
| 17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state including estimated date of starting any proposed work. If well is di measured and true vertical depths for all markers and zones portioned. | e all pertinent details, and give pertinent dates, |
| measured and true vertical depths for all markers and zones pertinent | t to this work.)* |
| | |
| 0/7/80 Surface casing point reached at 14 | . ८० । १ में में में में के होती |
| 0/7/80 Surface casing point reached at 14 8 5/8" 24# K-55 ST&C casing and se | Ran 35 joints (1451') |
| | |
| Followed by 200 sx Class 'C', 2% C throughout job. POB at 1:15 a.m. | Tacl Full Land 2 2% Cacl2. |
| throughout job. POB at 1:15 a.m. | 10/8/80 Woo 128 Table |
| Pressure tested casing at 1000 psi | for 30 minutes a definition |
| | |
| | 조선 동물함 사상 기행용확률 |
| | 경상을 높일 그렇게 일본학을 |
| | |
| · | |
| Subsurface Safety Valve: Manu. and Type | 그 그 그 그 이 이 이 이 이 이 이 이 이 이 이 이 이 이 이 이 |
| | Set @Ft. |
| 18. I hereby certify that the foregoing is true and correct | မ်းနှင့်ခွင်း နေသွာ မွေးကွဲမြို့ကြီး ကြောင်းသည် |
| SIGNED Ling Franklic TITLE Agent | DATE10/8/80 00000000000000000000000000000000 |
| ASCEPTED FOR REGORDace for Federal or State office | e use) |
| 1 // Charke | |
| CONDITIONS OF APPROVAL IF ANY: | DATE |
| OCT 1 5 1980 | |
| INC. OF OLD DOLL ALIDIUM | |
| U.S. GEOLOGICAL SURVEY | |
| ROSWELL, NEW MEXICO | |

RECEIVED

OCT 2 0 1980

O. C. D. ARTESIA, OFFICE

RECEIVED

OCT 2DEEC

OLCURAL.