

OIL CONSERVATION DIVISION

P. O. BOX 2088

SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-78

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease
State ☐ Fee ☒
5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator Western Reserves Oil Company	8. Farm or Lease Name RMM
3. Address of Operator P. O. Box 993, Midland, TX 79702	9. Well No. 1
4. Location of Well UNIT LETTER <u>P</u> , <u>330</u> FEET FROM THE <u>South</u> LINE AND <u>660</u> FEET FROM THE <u>East</u> LINE, SECTION <u>29</u> TOWNSHIP <u>7S</u> RANGE <u>31E</u> N.M.P.M.	10. Field and Pool, or WHdeat Tom-Tom (San Andres)
15. Elevation (Show whether DF, RT, GR, etc.) 4296.4' GR	12. County Chaves

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPERATIONS <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input checked="" type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

9/28/80 Spud 12 1/4" hole.

9/29/80 TD 1365'. Ran 33 joints (1344') 8 5/8" 24# casing. Set at 1361'. Cemented w/500 sx Halliburton Lite, 1/4# flocele/sx, 5# gilsonite/sx, 2% CaCl₂/sx. Followed by 200 sx Class 'C', 2% CaCl₂. Full circulation throughout job. Circulated 75 sx to surface. POB 1:45 a.m. 9/30/80. WOC 18 hrs. Pressure tested casing at 1000 psi for 30 minutes.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Jerry Frankler TITLE Agent DATE 9/30/80
Orig. Signed By
Jerry Sexton
APPROVED BY Dist. 1 Supv. TITLE _____ DATE OCT 2 1980
CONDITIONS OF APPROVAL, IF ANY: