Form 9-331 Dec. 1973	NM OIL CONS. COMMISSION Drawer DD -	Form Approved. Budget Bureau No. 42–R1424			
Dec. 1975	Artesiau, 20887AGES	ASE		(	-
	DEPARTMENT OF THE INTERIOR		<b>a</b>	<u> </u>	
	GEOLOGICAL SURVEY	<u>Ε.</u> IF INDIAN,		OR TRIBENDAME	ēD
SUNDR	Y NOTICES AND REPORTS ON WELLS	7. UNIT AGRE	EMENT NA	ME JUN 50 1	_ จุ <u>ิ</u> ภา
(Do not use this	s form for proposals to drill or to deepen or plug back to a different form 9–331–C for such proposals.)	8. FARM OR L	EASE NAMI	<u> </u>	<u> </u>
1. oil well	gas	<u>Champli</u> 9. WELL NO.	<u>سخ "ن</u>	ARTESAS OFF	
	F OPERATOR	#1	1612 1013	,bet	
Weste	ern Reserves Oil Compang	10. FIELD OR W	<u> </u>		
3. ADDRES	S OF OPERATOR	East Siet			<u> </u>
	. Box 2188 Hobbs, N.M. 88240				)R
4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.) 1980' FNL & 660' FEL		AREA Sec. 10,	. इ.ट. हे छे. <b>∓⊸8−</b> .S,	9 05.F	
AT SURFACE: Sec. 10, T-8-S, R-31-E		12. COUNTY OF		13 STATE	—
AT TOP PROD. INTERVAL:		Lea	5.3	NM	
ΑΤ ΤΟΤΑ	L DEPTH: 4070'	14. API NO.	2 = 4	E 0 7 5 6	
16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE,			2232		
REPORT,	OR OTHER DATA		2 2 2 2	DF KDB, AND WE	<b>)</b>
REQUEST FO	R APPROVAL TO: SUBSEQUENT REPORT OF:	4328.6	ĜR		
TEST WATER SHUT OFF			10 C 2 C 2		
			non hon qui	onlq s toor tools tools tools tools	
SHOOT OR ACIDIZE		•			
REPAIR WEL		(NOTE: Report n change (	esults of mul on Form 9–3	ltiple completion or zo 30.)은 - 국 및 동 문	
			೮೦೪ <u>ತೆ</u> ೧೯೮೭	30.) Inda Martha Martha Martha	riotrouz
CHANGE ZONES		- 		Hellon Hellon Hellon Hellon Hellon Hellon	Ē.
ABANDON*		2, **			
(other <u>) 503</u>	ridee cubing and comono		<u> </u>		<u> </u>
including	BE PROPOSED OR COMPLETED OPERATIONS (Clearly stat g estimated date of starting any proposed work. If well is d and true vertical depths for all markers and zones pertiner	irectionally drilled	tails, and , give subs	give pertinent date surface locations ar	⊧s, nd
		÷	•	÷ •	
5/18/81 Spud 12 1/4" hole @ 6:30 P.M.			3		
5/10/0.	1 Spud 12 1/4 Hote e 0.50 1.M.	i. Ç			
5/19/8	1 Surface casing point reached @	1478'. H	Ran 35	jts.	
-,,	8 5/8" 24# csg. Set @ 1478'.	Cemented	w/ 50(	) sx	
	Class "C", 5# gilsonite, 1/4#	flocele/s	and		
	2% CaCl. Followed by 200 sx C	lass "C" v	1/28 (	CaCl.	
	Circulated 60 sx to surface.	Full circu	ilation	n thruout	
	job. POB @ 5:30 A.M. 5/20/81			승규는 정말을 받았다.	
		÷		· 이상· · · · · · · · · · · · · · · · · ·	
				· · · · · · · · · · · · · · · · · · ·	
Subsurface S	Safety Valve: Manu. and Type	· · · · · · · · · · · · · · · · · · ·	Set (	@I	Ft.
18. I hereby	certify that the foregoing is true and correct				
SIGNED	TITLE Agent	DATE	ine 25	, 1981	
	ACCEPTED FOR RECORD (This space for Federal or State of			······································	-
APPROVED RY	ROGER A. CHAPMAN				
CONDITIONS	PF APPROVAL, IF ANY:	รักฐา	ନ୍ଦନ୍ଦ୍ରମ	775 กา	
	JUN 2.9 1981		नरगर	wrd 111 -	
			UN-2-6	1981	
	U.S. GEOLOGICAL SURVEY	side		111	
	ROSWELL, NEW MEXICO		OIL & GAS GEOLOGICAL	SURVEY	
			VI. CHA		

•

•

## .

## 14 M A ¥1, 21

• **.** . .

## JUL 11981