

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYOIL CONS. COMMISSION
Drawer DD
Artesia, NM

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)

1. oil ☒ well gas ☐ well other ☐2. NAME OF OPERATOR
Exxon Corporation3. ADDRESS OF OPERATOR
P. O. Box 1600, Midland, Texas 797024. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)
AT SURFACE: 1980' FSL and 660' FWL of Sec.
AT TOP PROD. INTERVAL:
AT TOTAL DEPTH:

16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

REQUEST FOR APPROVAL TO:

TEST WATER SHUT-OFF ☐
FRACTURE TREAT ☐
SHOOT OR ACIDIZE ☐
REPAIR WELL ☐
PULL OR ALTER CASING ☐
MULTIPLE COMPLETE ☐
CHANGE ZONES ☐
ABANDON* ☐
(other) ☐

SUBSEQUENT REPORT OF:

☒
☐
☐
☐
☐
☐
☐
☐

(NOTE: Report results of multiple completion or zone change on Form 9-330.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Spudded 12 1/4" hole 3:00 p.m. 10-28-81.
Drilled 12 1/4" hole to 1330'.
Ran 30 jts 1317' 8 5/8" 24# csg set at 1330'
Cmt w/600 sx Halilite, Tailed w/250 sx C1 "C" cmt.
Plug down 2:15 a.m. 10-30-81. circ 170 sx.
Tested 8 5/8" csg at 8:15 p.m. 10-30-81 w/1000# for 30 min. - held ok

Subsurface Safety Valve: Manu. and Type _____ Set @ _____ Ft.

18. I hereby certify that the foregoing is true and correct

SIGNED ROGER A. CHAPMANTITLE Sr. Administrator DATE 11-10-81

(This space for Federal or State office use)

APPROVED BY NOV 16 1981
CONDITIONS OF APPROVAL IF ANY:
U.S. GEOLOGICAL SURVEY
ROSWELL, NEW MEXICO

