

UNITED STATES DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY
NM OIL CONS. COMMISSION
Drawer DD
Roswell, NM 88210

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)

1. oil ☒ well gas ☐ well other ☐
2. NAME OF OPERATOR
MIRANDA ENERGY
3. ADDRESS OF OPERATOR 79701
105 West Wall St. Suite 800 Midland, TX
4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)
AT SURFACE: 1980' FSL & 680' FWL Sec22
AT TOP PROD. INTERVAL: Same
AT TOTAL DEPTH: Same
16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

- REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF:
- | | | |
|----------------------|-------------------------------------|-------------------------------------|
| TEST WATER SHUT-OFF | <input type="checkbox"/> | <input type="checkbox"/> |
| FRACTURE TREAT | <input type="checkbox"/> | <input type="checkbox"/> |
| SHOOT OR ACIDIZE | <input type="checkbox"/> | <input type="checkbox"/> |
| REPAIR WELL | <input type="checkbox"/> | <input type="checkbox"/> |
| PULL OR ALTER CASING | <input type="checkbox"/> | <input type="checkbox"/> |
| MULTIPLE COMPLETE | <input type="checkbox"/> | <input type="checkbox"/> |
| CHANGE ZONES | <input type="checkbox"/> | <input type="checkbox"/> |
| ABANDON* | <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> |
- (other)


5. LEASE
NM 31189
6. IF INDIAN, ALLOTTEE OR TRIBE NAME
N/A
7. UNIT AGREEMENT NAME
N/A
8. FARM OR LEASE NAME
Federal
9. WELL NO.
1-Y
10. FIELD OR WILDCAT NAME
SIETE EXTENSION
11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA
Sec 22, T-8-S, R-31-E
12. COUNTY OR PARISH
Chaves
13. STATE
N.M.
14. API NO.
N/A
15. ELEVATIONS (SHOW DF, KDB, AND WD)
4265 GR

(NOTE: Report results of multiple completion or zone change on Form 9-330.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Well P & A on 8-28-81 because no Productive Zones were encountered.
Well was plugged as follows with 10.2 #/gal. mud between plugs.

75 sx. cement plug at 3700' - 3862'
50 sx. cement plug at 1930' - 2030'
50 sx. cement plug at 1350' - 1450'
10 sx. cement plug at surface
Marker installed



OIL & GAS
U.S. GEOLOGICAL SURVEY
ROSWELL, NEW MEXICO

Subsurface Safety Valve; Manu. and Type _____ Set @ _____ Ft.

18. I hereby certify that the foregoing is true and correct

SIGNED J. C. Raney TITLE Agent DATE 9-11-81

(This space for Federal or State office use)

APPROVED BY (Orig. Sgd.) PLTER W. CLUSTER TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY:

NOV 29 1982

FOR
JAMES A. GILLHAM
DISTRICT SUPERVISOR

*See Instructions on Reverse Side

RECEIVED

DEC 3 1982

C.C.D.
HOBBS OFFICE