

NO. OF TUBES PER WELL	
DISTRICT	
TANKAGE	
WELL	
U.S. 104	
LAND OFFICE	
OPERATOR	

1. Indicate the type of device
State Flow

2. State the name of the well

Broke Tank
1
Wildcat
Chaves

STIMULY NOTICE AND REPORT ON WELLS

Harvey E. Yates Company
P. O. Box 1933, Roswell, NM 88201

1980 South 1980
East 7 9S 30E

4019.5' GL

Check Appropriate Box To Indicate Nature of New Report of Test Data
STIMULY REPORT

13 3/8" csg

- 1/7/82 Depth 260', formation - Red Bed & Anhy. RU to run 13 3/8" OD csg.
- 1/8/82 Ran 257.50' of 13 3/8" OD, 54.4#/ft, J-55, New ST&C csg, Set @ 257'. Shoe @ 257', FC @ 223'.
- 1/9/82 Cemented w/250 sxs Class "C" w/2% CaCl. Plug down @ 1:00 p.m. Circ 25 sx to pit. WOC.

Paul Sander

Engineer

DATE 1/13/82

Orig. Signed by
Jerry Sexton
Dist. Supt.