

UNITED STATES DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY
N. M. OIL CONS. COMMISSION
P. O. BOX 1930
ALBUQUERQUE, NEW MEXICO 87103

Form Approved.
Budget Bureau No. 42-R1424

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)

1. oil well ☐ gas well ☐ other ☒ Conductor pipe
2. NAME OF OPERATOR
M. J. Harvey, Jr.
3. ADDRESS OF OPERATOR
Box 12705 Dallas, Texas 75225
4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)
AT SURFACE: 1985' FWL & 660' FNL
AT TOP PROD. INTERVAL:
AT TOTAL DEPTH: NA

16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

REQUEST FOR APPROVAL TO:

SUBSEQUENT REPORT OF:

TEST WATER SHUT-OFF ☐
FRACTURE TREAT ☐
SHOOT OR ACIDIZE ☐
REPAIR WELL ☐
PULL OR ALTER CASING ☐
MULTIPLE COMPLETE ☐
CHANGE ZONES ☐
ABANDON* ☐

☐
☐
☐
☐
☐
☐
☐
☒

(other) LOCATION RESTORATION

88240 CASE
NM-15020
6. IF INDIAN, ALLOTTEE OR TRIBE NAME
7. UNIT AGREEMENT NAME
8. FARM OR LEASE NAME
Harvey Federal
9. WELL NO.
#1
10. FIELD OR WILDCAT NAME
Chaveroo
11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA
Sec. 24-T8S-R32E
12. COUNTY OR PARISH 13. STATE
Chaves New Mexico
14. API NO.
15. ELEVATIONS (SHOW DF, KDB, AND WD)
4425' GR

(NOTE: Report results of multiple completion or zone change on Form 9-330.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Please be advised that the subject location was restored and is now ready for your final inspection. A landowner clearance letter will be submitted to your office in the near future from the surface owner, Davis Brothers Ranches. As conductor pipe only was set, restoration consisted of filling the 40' of 20" with dirt, cutting pipe below ground level and leveling the disturbed area. No location had been built.

Subsurface Safety Valve: Manu. and Type _____ Set @ _____ Ft.

18. I hereby certify that the foregoing is true and correct

SIGNED Jerry E. Keeler TITLE Agent

DATE 6/7/82

APPROVED BY _____ TITLE _____

CONDITIONS OF APPROVAL, IF ANY:

ACCEPTED FOR RECORD

PETER W. CHESTER

JUN 11 1982

U.S. GEOLOGICAL SURVEY
ROSWELL, NEW MEXICO

See Instructions on Reverse Side

