

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)

1. oil ☒ gas ☐
well well other

2. NAME OF OPERATOR

Yates Petroleum Corporation

3. ADDRESS OF OPERATOR

207 South 4th St., Artesia, NM 88210

4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)

AT SURFACE: 330 FNL & ^{FEL} ~~FNL~~, Sec. 1-8S-31E

AT TOP PROD. INTERVAL:

AT TOTAL DEPTH:

16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

REQUEST FOR APPROVAL TO:

TEST WATER SHUT-OFF ☐

FRACTURE TREAT ☐

SHOOT OR ACIDIZE ☐

REPAIR WELL ☐

PULL OR ALTER CASING ☐

MULTIPLE COMPLETE ☐

CHANGE ZONES ☐

ABANDON* ☐

(other) ☐

SUBSEQUENT REPORT OF:

☒

☐

☐

☐

☐

☐

☐

☐

☐

5. LEASE 0558018

NM 0558108

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Union SI Federal

9. WELL NO.

4

10. FIELD OR WILDCAT NAME

Und. Tomahawk SA

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA

Unit A, Sec. 1-T8S-R31E

12. COUNTY OR PARISH 13. STATE

Chaves

NM

14. API NO.

15. ELEVATIONS (SHOW DF, KDB, AND WD)

4419.4' GR

(NOTE: Report results of multiple completion or zone change on Form 9-330.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Spudded a 12-1/4" hole 10:00 AM 7-10-82. Set 40' of 14" conductor pipe. Ran 43 joints of 8-5/8" 24# J-55 casing set at 1700'. 1-Texas Pattern guide shoe set 1700'. Insert float at 1662'. Cemented w/400 sacks Pacesetter Lite with 3% CaCl. Tailed in w/350 sacks Class "C" with 2% CaCl. Compressive strength of cement - 1250 psi in 12 hours. PD 10:32 AM 7-14-82. Bumped plug to 1000 psi, released pressure and float held okay. Cement circulated 35 sacks. WOC. Drilled out 4:30 AM 7-15-82. WOC 18 hours. Nippled up and tested to 1000#, okay. Reduced hole to 7-7/8". Drilled plug and resumed drilling.

Subsurface Safety Valve: Manu. and Type

Set @ Ft.

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE

Engineering Secty

DATE

7-16-82

(This space for Federal or State office use)

APPROVED BY

CONDITIONAL ACCEPTANCE FOR RECORD

TITLE

DATE

A.R.G.
SEP 29 1982

*See Instructions on Reverse Side

U.S. GEOLOGICAL SURVEY
ROSWELL, NEW MEXICO

RECEIVED
JUL 19 1982

OIL & GAS
U.S. GEOLOGICAL SURVEY

RECEIVED
SEP 30 1982
FBI - BUREAU
FBI - BUREAU OFFICE