

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYN. M. O. C. C. COPY
SUBMIT IN TRIPLICATE*
(Other instructions on
reverse side)Form approved.
Budget Bureau No. 42-R1424.

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER		5. LEASE DESIGNATION AND SERIAL NO. 1M0256521 & B
2. NAME OF OPERATOR Yates Drilling Company		6. IF INDIAN, ALLOTTEE OR TRIBAL NAME
3. ADDRESS OF OPERATOR 207 South 4th Street - Artesia, New Mexico 88210		7. UNIT AGREEMENT NAME
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface 1980' FML & 990' FEL of Sec. 4-13S-31E		8. FARM OR LEASE NAME Federal AA
14. PERMIT NO.		9. WELL NO. 1
15. ELEVATIONS (Show whether DF, RT, GR, etc.) 4112' GR		10. FIELD AND TOOL, OR WILDCAT Wildcat
		11. SEC. T. R. M. OR BLK. AND SURVEY OR AREA Sec. 4-13S-31E Unit H. NMMP
		12. COUNTY OR PARISH 13. STATE Chaves NM

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data.

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
TEST WATER SHUT-OFF	<input type="checkbox"/>	WATER SHUT-OFF	<input type="checkbox"/>
FRACTURE TREAT	<input type="checkbox"/>	FRACTURE TREATMENT	<input type="checkbox"/>
SHOOT OR ACIDIZE	<input type="checkbox"/>	SHOOTING OR ACIDIZING	<input type="checkbox"/>
REPAIR WELL	<input type="checkbox"/>	(Other) Spud & Set Surface Csg.	<input checked="" type="checkbox"/>
(Other)	<input type="checkbox"/>	(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)	

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.) *

4-27-72 - Spudded 3:00 PM 4-26-72.

TD 337' - Drilled 11" hole to 337', ran 325' of 8 5/8" 20# J-55 casing, 1-Tex Pattern Shoe set at 323' GL with 150 sacks of Incor 4% CaCl cement. Cement circulated. PD 7:30 PM 4-26-72. WOC 12 hrs. Nipped up and tested casing with 1000#. Tested OK. Drilled plug, reduced hole to 7 7/8" and resumed drilling.

RECEIVED
MAY - 11 1972
U. S. GEOLOGICAL SURVEY
ARTESIA, NEW MEXICO18. I hereby certify that the foregoing is true and correct.
SIGNED Clinton L. Lyle TITLE District Supt. DATE 5-1-72
(This space for Federal or State office use)APPROVED BY
CONDITIONS OF APPROVAL, IF ANY:

TITLE

DATE

*See Instructions on Reverse Side

RECEIVED

MAY 3 1972

OIL CONSERVATION COMM.
HOBBS, N. M.