

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

OIL CONSERVATION DIVISION
P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-78

5a. Indicate Type of Lease
State ☒ Fee ☐
5. State Oil & Gas Lease No.
V-1146

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator Upland Production Co.	8. Farm or Lease Name Mize-State
3. Address of Operator P.O. Box 481 Midland, Texas 79702	9. Well No. 1
4. Location of Well UNIT LETTER M 330 FEET FROM THE West LINE AND 660 FEET FROM THE South LINE, SECTION 35 TOWNSHIP 12S RANGE 31E NMPM.	10. Field and Pool, or Wildcat SE Chaves Queen
15. Elevation (Show whether DF, RT, CR, etc.) 4421.6 G.L.	12. County Chaves

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input checked="" type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

10-28-84 T.D. 3101'. Ran 74 joints 5½"-15.5#-J-55, new casing set at 3101', 5 centralizers, guide shoe @3101'-insert float @ 3057.5'. Cemented with, lead 610 sx. HE lite 4 with 5# salt per sx. tailin 200 sx. HE II + 2% CaCl & ¼# celloflakes/sx. Plug down 12:20 A.M. Bumped plug @ 2000 # released pressure-checked for 30 min, held O.K. W.O.C. 18 hrs.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED W. B. McCarty TITLE Agent DATE 11/15/84
ORIGINAL SIGNED BY GERRY SEXTON
APPROVED BY DISTRICT 1 SUPERVISOR TITLE DATE NOV 15 1984
CONDITIONS OF APPROVAL, IF ANY: