

UNITED STATES DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY
NEW MEXICO OIL CONS. COMMISSION
Artesia, NM 88210
Drawer DD

Form Approved
Budget Bureau No. 42-R1424

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)

1. oil well ☒ gas well ☐ other ☐

2. NAME OF OPERATOR

Yates Drilling Company

3. ADDRESS OF OPERATOR

207 South 4th Street, Artesia, N.M. 88210

4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)

AT SURFACE: 1980' FNL and 1650' FWL

AT TOP PROD. INTERVAL:

AT TOTAL DEPTH:

16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

REQUEST FOR APPROVAL TO:

SUBSEQUENT REPORT OF:

TEST WATER SHUT-OFF ☐

FRACTURE TREAT ☐

SHOOT OR ACIDIZE ☐

REPAIR WELL ☐

PULL OR ALTER CASING ☐

MULTIPLE COMPLETE ☐

CHANGE ZONES ☐

ABANDON* ☐

(other) ☐

5. LEASE

NM-015807

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Garner Federal

9. WELL NO.

8

10. FIELD OR WILDCAT NAME

S.E. Chaves Queen Gas Area Assoc.

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA

Sec. 3-T13S-R31E

12. COUNTY OR PARISH

Chaves

13. STATE

N.M.

14. API NO.

15. ELEVATIONS (SHOW DF, KDB, AND WD)

4188.2' GL

(NOTE: Report results of multiple completion or zone change on Form 9-330.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Spudded 12 1/4" hole, 11-4-84.

Ran 9 joints 8 5/8" 24# J-55 ST&C casing set at 382'. 1-Regular Pattern notched shoe set at 382'. Auto-fill Insert float set 340'. Cemented with 250 sacks Class "C" 3% CaCl₂, 1/4#/sack flocele. Compressive strength of cement 1275 psi in 12 hours. PD 12:41 AM, 11-5-84. Bumped plug to 1000 psi, released pressure and float held okay. Cement circulated 50 sacks to pit. WOC 12 hours, 49 minutes. Drilled out 1:30 PM, 11-5-84. Reduced hole to 7 7/8". Drilled plug and resumed drilling.

Subsurface Safety Valve: Manu. and Type

Set @ . . . Ft.

18. I hereby certify that the foregoing is true and correct

SIGNED

Ken Lushman

TITLE Production Clerk DATE 11-8-84

ACCEPTED FOR RECORD (This space for Federal or State office use)

APPROVED BY
CONDITIONS OF APPROVAL, IF ANY:

PETER W. CHESTER

NOV 21 1984

TITLE

DATE

RECEIVED BY
NOV 27 1984
O. C. D.
ARTESIA, OFFICE

RECEIVED
DEC - 3 1984