

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

| |
|---|
| WELL API NO. 30-005-21038 |
| 5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/> |
| 6. State Oil & Gas Lease No. E-8250 |
| 7. Lease Name or Unit Agreement Name Enstar ACW State |
| 8. Well No. 1 |
| 9. Pool name or Wildcat Undesignated San Andres |

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

| |
|--|
| 1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER Plugback & Recomplete |
| 2. Name of Operator YATES PETROLEUM CORPORATION |
| 3. Address of Operator 105 South 4th St., Artesia, NM 88210 |
| 4. Well Location Unit Letter <u>I</u> : 1980 Feet From The <u>South</u> Line and <u>660</u> Feet From The <u>East</u> Line Section <u>27</u> Township <u>8</u> Range <u>33</u> NMPM <u>Chaves</u> County |
| 10. Elevation (Show whether DF, RKB, RT, GR, etc.) 4356' GR |

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

| NOTICE OF INTENTION TO: | SUBSEQUENT REPORT OF: |
|--|--|
| PERFORM REMEDIAL WORK <input type="checkbox"/> | REMEDIAL WORK <input type="checkbox"/> |
| TEMPORARILY ABANDON <input type="checkbox"/> | ALTERING CASING <input type="checkbox"/> |
| PULL OR ALTER CASING <input type="checkbox"/> | COMMENCE DRILLING OPNS. <input type="checkbox"/> |
| OTHER: <input type="checkbox"/> | PLUG AND ABANDONMENT <input type="checkbox"/> |
| | CASING TEST AND CEMENT JOB <input type="checkbox"/> |
| | OTHER: Plugback, test San Andres <input checked="" type="checkbox"/> |

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

8-23-89. RUPU & install BOP. Pumped dn csg w/100 bbls wtr. No returns on 8-5/8"x5 1/2" annulus. WIH w/bit to 4874' & set down. Pulled bit.

8-24-89. WIH w/pkr & set @4742'. Loaded annulus & tested to 1000#, OK. Loaded & pumped dn tbg 750# @4BPM. Obtained approval from Jerry Sexton, NMOC, Hobbs, to plug lower portion of well and recomplete in San Andres. Pumped 200 sx Cl C+.4% fluid loss additive dn tbg & displaced cmt past pkr w/23 1/2 bbls (to 6000'). Pump in pressure 1000#. Tubing-csg annulus held OK. No returns on 8-5/8"x5 1/2" casing annulus. SION.

8-25-89. Loaded tbg w/1/2 bbl. Pressured to 500#, held OK. Pull pkr & TIH w/tbg open-ended. Spot plug from 4871-4771'. WOC & tag plug @4730'. Perforate 4675 & 4725' w/4 shots. Could not pump in perfs at 3500#. SD due to muddy roads.

9-6-89. Ran CBL. Showed bridge 4550-4600'. Perforated San Andres P₂ 4570-76' w/12 .42" holes (2 SPF). 8-5/8"-5 1/2" annulus holding.

9-8-89. TIH w/pkr & tbg dry. Dropped bar & knocked out pkr disc. WIH swab. Found 200' water entry. 8-5/8"x5 1/2" annulus - no change. (continued page 2)

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Juanita Goodlett TITLE Production Supervisor DATE 9-11-89

TYPE OR PRINT NAME Juanita Goodlett TELEPHONE NO. 505/748-1471

(This space for State) **ORIGINAL SIGNED BY JERRY SEXTON**
DISTRICT I SUPERVISOR

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY:

SEP 13 1989

RECEIVED

SEP 12 1989

OCD
MOBBS OFFICE

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

| | |
|------------------------------|--|
| WELL API NO. | 30-005-21038 |
| 5. Indicate Type of Lease | STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/> |
| 6. State Oil & Gas Lease No. | E-8250 |

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

| | |
|--------------------------------------|-------------------------|
| 7. Lease Name or Unit Agreement Name | Enstar ACW State |
| 8. Well No. | 1 |
| 9. Pool name or Wildcat | Undesignated San Andres |

| | |
|------------------------|--|
| 1. Type of Well: | OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER Plugback & Recomplete |
| 2. Name of Operator | YATES PETROLEUM CORPORATION |
| 3. Address of Operator | 105 South 4th St., Artesia, NM 88210 |

| | |
|------------------|--|
| 4. Well Location | Unit Letter <u>I</u> : <u>1980</u> Feet From The <u>South</u> Line and <u>660</u> Feet From The <u>East</u> Line |
| | Section <u>27</u> Township <u>8S</u> Range <u>33E</u> NMPM <u>Chaves</u> County |

| | |
|--|----------|
| 10. Elevation (Show whether DF, RKB, RT, GR, etc.) | 4356' GR |
|--|----------|

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

| NOTICE OF INTENTION TO: | | SUBSEQUENT REPORT OF: | |
|--|---|---|---|
| PERFORM REMEDIAL WORK <input type="checkbox"/> | PLUG AND ABANDON <input type="checkbox"/> | REMEDIAL WORK <input type="checkbox"/> | ALTERING CASING <input type="checkbox"/> |
| TEMPORARILY ABANDON <input type="checkbox"/> | CHANGE PLANS <input type="checkbox"/> | COMMENCE DRILLING OPNS. <input type="checkbox"/> | PLUG AND ABANDONMENT <input type="checkbox"/> |
| PULL OR ALTER CASING <input type="checkbox"/> | | CASING TEST AND CEMENT JOB <input type="checkbox"/> | |
| OTHER: <input type="checkbox"/> | | OTHER: <input type="checkbox"/> | |

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

(continued from page 2) 9-8-89. Acidized perms 4570-76' w/500 gals 20% NEFE. Treating pressures: Avg 2600-3200# @ 0.4 BPM. ISDP 2500#, 15 mins 1300#. Swabbed load plus 52 bbls. Final fluid level 4300'. No show oil or gas. 8-5/8"x5 1/2" - no change.

9-9-89. Set CIBP @ 4565' & perforate 4536-40' w/8 - .42" holes (2 SPF). Broke circulation between 8-5/8"-51/2" annulus. Set retainer at 4525'. Cemented w/300 sx C1 C w/1000 gals mud flush ahead. WOC.

9-11-89. Perforate San Andres P₁ w/16 .42" holes as follows: 4481, 82, 85, 87, 88, 89, 90, 92, 93, 96, 98, 99, 4500, 01, 08, and 4509'. TIH w/pkr and acidize w/2000 gals 20% NEFE. Testing well.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Juanita Goodlett TITLE Production Supervisor DATE 9-11-89

TYPE OR PRINT NAME Juanita Goodlett TELEPHONE NO. 505/748-1471

(This space for State Use)

ORIGINAL SIGNED BY JERRY SEXTON
DISTRICT I SUPERVISOR

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY:

SEP 13 1989

RECEIVED

SEP 12 1939

OFF
MONTGOMERY