

NO. OF COPIES RECEIVED		
DISTRIBUTION		
SANTA FE		
FILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR		

NEW MEXICO OIL CONSERVATION COMMISSION

JUL 28 3 22 AM '69

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.	
E-9171	

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. <input type="checkbox"/> OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- Injection Well		7. Unit Agreement Name
2. Name of Operator		8. Farm or Lease Name
GREAT WESTERN DRILLING COMPANY		Sec. 5
3. Address of Operator		9. Well No.
P. O. Box 1659, Midland, Texas 79701		6
4. Location of Well		10. Field and Pool, or Wildcat
UNIT LETTER F , 1980 FEET FROM THE North LINE AND 1980 FEET FROM		Caprock Queen
THE West LINE, SECTION 5 TOWNSHIP 13-S RANGE 32-E NMPM.		
15. Elevation (Show whether DF, RT, GR, etc.)		12. County
4353 GR		Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

On March 22, 1969, the hole was loaded with mud. A 50 sack cement plug was spotted @ 3035'. 1030' of 5½" was pulled. 25 sack cement plugs were spotted in the stub of the 5½" and in the 8 5/8" @ 305'. 10 sacks were placed at the surface. A cleanup will be made when equipment is removed.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED O. H. Crews TITLE Administrative Coordinator DATE July 28, 1969

APPROVED BY John W. Runyan TITLE Geologist DATE 1969

CONDITIONS OF APPROVAL, IF ANY: