

CORRECTED REPORT

NUMBER OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
TRANSPORTER	OIL
	GAS
PRODUCTION OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

FORM C-103
(Rev 3-55)

MISCELLANEOUS REPORTS ON WELLS

(Submit to appropriate District Office as per Commission Rule 1106)

Name of Company Graridge Corporation		1962 AUG 9 Drawer B, Artesia, New Mexico	
Lease Cap Unit #1	Well No. 7-8B	Unit Letter H	Section 7
Date Work Performed 8-10-61		Pool Caprock Queen	Township 138
		Range 32E	
		County Lea	

THIS IS A REPORT OF: (Check appropriate block)

- ☐ Beginning Drilling Operations
 ☐ Casing Test and Cement Job
 ☐ Other (Explain):
- ☒ Plugging
 ☐ Remedial Work

Detailed account of work done, nature and quantity of materials used, and results obtained.

Hole had to be plugged after unsuccessful attempt was made to set a liner. Liner was cemented in bottom of hole with 175 sacks cement. Loaded hole with drilling mud. 5 1/2" casing was collapsed at 460'. Spotted 35 sacks cement in 5 1/2" casing from 460' to 300'. Spotted 10 sacks cement in top of 5 1/2" casing and set regulation marker.

Witnessed by B. I. Miller	Position Engineer	Company Graridge Corporation
-------------------------------------	-----------------------------	--

FILL IN BELOW FOR REMEDIAL WORK REPORTS ONLY

ORIGINAL WELL DATA

D F Elev.	T D	P B T D	Producing Interval	Completion Date
Tubing Diameter	Tubing Depth	Oil String Diameter	Oil String Depth	
Perforated Interval(s)				
Open Hole Interval		Producing Formation(s)		

RESULTS OF WORKOVER

Test	Date of Test	Oil Production BPD	Gas Production MCFPD	Water Production BPD	GOR Cubic feet/Bbl	Gas Well Potential MCFPD
Before Workover						
After Workover						

OIL CONSERVATION COMMISSION		I hereby certify that the information given above is true and complete to the best of my knowledge.	
Approved by		Name <i>J. C. Chapman</i>	
Title		Position J. C. Chapman Engineer	
Date		Company Graridge Corporation	