

NUMBER OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
TRANSPORTER	OIL GAS
PRODUCTION OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

FORM C-103
(Rev 3-55)

MISCELLANEOUS REPORTS ON WELLS

(Submit to appropriate District Office as per Commission Rule 1106)

Name of Company Graridge Corporation				Address Drawer B, Artesia, New Mexico			
Lease Cap Unit #1		Well No. 7-8B	Unit Letter H	Section 7	Township 13E	Range 32E	
Date Work Performed 8-21-61		Pool Caprock Queen			County Lea		

THIS IS A REPORT OF: (Check appropriate block)

- ☐ Beginning Drilling Operations
 ☐ Casing Test and Cement Job
 ☐ Other (Explain):
- ☒ Plugging
 ☐ Remedial Work

Detailed account of work done, nature and quantity of materials used, and results obtained.

After drilling to TD 2100' drill pipe became stuck at 1260' while pulling. Failing to retrieve all pipe the well was plugged. Remaining stuck drill pipe sets from 915' to 1260'. Ran 3 1/2" drill pipe in hole to 915'. Halliburton spotted 40 sack cement plug at 915', 25 sack cement plug at 325', and 10 sack cement plug at surface. Set regulation marker and cleared location.

Witnessed by B. I. Miller	Position Engineer	Company Graridge Corporation
-------------------------------------	-----------------------------	--

FILL IN BELOW FOR REMEDIAL WORK REPORTS ONLY

ORIGINAL WELL DATA

D F Elev.	T D	P B T D	Producing Interval	Completion Date
Tubing Diameter	Tubing Depth	Oil String Diameter	Oil String Depth	
Perforated Interval(s)				
Open Hole Interval		Producing Formation(s)		

RESULTS OF WORKOVER

Test	Date of Test	Oil Production BPD	Gas Production MCFPD	Water Production BPD	GOR Cubic feet/Bbl	Gas Well Potential MCFPD
Before Workover						
After Workover						

OIL CONSERVATION COMMISSION

I hereby certify that the information given above is true and complete to the best of my knowledge.

Approved by <i>Lesho A. Clements</i>	Name <i>J. C. Chapman</i>
Title	Position J. C. Chapman Engineer
Date	Company Graridge Corporation