

NUMBER OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
TRANSPORTER	OIL
	GAS
PRORATION OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

FORM C-103
(Rev 3-55)

MISCELLANEOUS REPORTS ON WELLS

(Submit to appropriate District Office as per Commission Rule 1106)

Name of Company Graridge Corporation				Address Box 334, Caprock, New Mexico			
Lease Cap Unit #1	Well No. 7-8A	Unit Letter H	Section 7	Township 13S	Range 32E		
Date Work Performed 7-19-61	Pool Caprock Queen			County Lea			

THIS IS A REPORT OF: (Check appropriate block)

- ☐ Beginning Drilling Operations
 ☐ Casing Test and Cement Job
 ☐ Other (Explain):
- ☒ Plugging
 ☐ Remedial Work

Detailed account of work done, nature and quantity of materials used, and results obtained.

Well lost due to stuck drill pipe at 1260 feet. T.D. 2100'. Member of Oil Conservation Commission witnessed plugging of well. Spot and displace with pump--100 sacks regular cement at 960'. Spot 25 sacks cement at base of surface casing at 300'. 10 sacks in top of surface with proper marker.

Witnessed by B. I. Miller	Position Engineer	Company Graridge Corporation
-------------------------------------	-----------------------------	--

FILL IN BELOW FOR REMEDIAL WORK REPORTS ONLY

ORIGINAL WELL DATA

D F Elev.	T D	P B T D	Producing Interval	Completion Date
Tubing Diameter	Tubing Depth	Oil String Diameter	Oil String Depth	
Perforated Interval(s)				
Open Hole Interval		Producing Formation(s)		

RESULTS OF WORKOVER

Test	Date of Test	Oil Production BPD	Gas Production MCFPD	Water Production BPD	GOR Cubic feet/Bbl	Gas Well Potential MCFPD
Before Workover						
After Workover						

OIL CONSERVATION COMMISSION

I hereby certify that the information given above is true and complete to the best of my knowledge.

Approved by <i>Leslie A. Clements</i>	Name <i>B. I. Miller</i>
Title	Position B. I. Miller Engineer
Date	Company Graridge Corporation