

# OIL CONSERVATION COMMISSION

## Santa Fe, New Mexico

## MISCELLANEOUS REPORTS ON WELLS

Submit this report in triplicate to the Oil Conservation Commission or its proper agent within ten days after the work specified is completed. It should be signed and sworn to before a notary public for reports on beginning drilling operations, results of shooting well, results of test of casing shut off, result of plugging of well, and other important operations, even though the work was witnessed by an agent of the Commission. Reports on minor operations need not be signed and sworn to before a notary public. See additional instructions in the Rules and Regulations of the Commission.

**Indicate nature of report by checking below.**

REPORT ON BEGINNING DRILLING OPERATIONS	I	REPORT ON REPAIRING WELL
REPORT ON RESULT OF SHOOTING OR CHEMICAL TREATMENT OF WELL		REPORT ON PULLING OR OTHERWISE ALTERING CASING
REPORT ON RESULT OF TEST OF CASING SHUT-OFF		REPORT ON DEEPENING WELL
REPORT ON RESULT OF PLUGGING OF WELL		

Midland, Texas March 16, 1948

**OIL CONSERVATION COMMISSION,  
SANTA FE, NEW MEXICO**  
Gentlemen:

Following is a report on the work done and the results obtained under the heading noted above at the\_\_\_\_\_

I. L. Wilson Drilling Company State Well No. 1 in the  
Company or Operator Lease  
NE<sup>1</sup>/<sub>4</sub> of NW<sup>1</sup>/<sub>4</sub> of Sec. 19, T. 13 S, R. 32 E, N. M. P. M.,  
Caprock Field, Lea County, New Mexico County.

The dates of this work were as follows: 30 qt. shot March 5, swabbing & testing March 6-10  
Notice of intention to do the work was (was ~~not~~) submitted on Form C-102 on March 2 1948  
and approval of the proposed plan was (was not) obtained. (Cross out incorrect words.)

### DETAILED ACCOUNT OF WORK DONE AND RESULTS OBTAINED

30 qt. liquid nitro-glycerin shot was placed 3058' to 3060' on Mar. 5 tamped with gravel and cal-seal plug and hole filled with oil to top. after shot well was swabbed through casing for two days recovering approx. 180 bbls. of oil. During second day swabbing it was discovered that a small amount of redbed formation and water were getting into the hole through the casing. Test was run by Dowell and a leak discovered in casing from 1267' to 1278'. Pipe was not collapsed but appears to be split. Clean out work has been suspended and preparations being made to squeeze cement on split pipe.

Witnessed by R. E. Throckmorton H. L. Wilson Drilling Co. Partner

Name	Company	Title
R. E. Throckmorton	H. L. Wilson Drilling Co.	Partner

Subscribed and sworn before me this \_\_\_\_\_

17 day of March 1948

Miss Johnson

I hereby swear or affirm that the information given above is true and correct.

Name E. Brockman

Position Tarstner

Representing H. L. Wilson Drilling Company  
Company or Operator

Address Box 1517 Midland, Texas.

H. D. JOHNSON, Notary Public  
MIDLAND COUNTY, TEXAS

My commission expires 6-1-49

**Remarks:**

APPROVED

Date: MAR 18 1948

Page 12/12

**Name**  
**OIL & GAS INSPECTOR**

**Title**