

NO. OF COPIES RECEIVED		
DISTRIBUTION		
SANTA FE		
FILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR		

OIL CONSERVATION DIVISION
P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-78

5a. Indicate Type of Lease
State ☒ Fee ☐

5. State Oil & Gas Lease No.
B10083

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. ☒ OIL WELL ☐ GAS WELL ☐ OTHER-
2. Name of Operator
Amerada Hess Corporation
3. Address of Operator
Drawer D, Monument, New Mexico 88265
4. Location of Well
UNIT LETTER N 660 FEET FROM THE South LINE AND 1980 FEET FROM
THE West LINE, SECTION 23 TOWNSHIP 12-S RANGE 33-E N.M.P.M.

7. Unit Agreement Name
8. Farm or Lease Name
State BT "E"
9. Well No.
1
10. Field and Pool, or Wildcat
Lightwater Perm
12. County
Lea

15. Elevation (Show whether DF, RT, GR, etc.)
4632' DF.

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK ☐	PLUG AND ABANDON ☐	REMEDIAL WORK ☒	ALTERING CASING ☐
TEMPORARILY ABANDON ☐	CHANGE PLANS ☐	COMMENCE DRILLING OPNS. ☐	PLUG AND ABANDONMENT ☐
PULL OR ALTER CASING ☐	OTHER ☐	CASING TEST AND CEMENT JOBS ☐	OTHER ☒ Zone abandonment

17. Describe Prepared or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Pulled 2-3/8" tbg. & pkr. Ran 4-3/4" drlg. bailer & cleaned out cement inside 5 1/2" csg. fr. 8789' to 8800' & knocked bridge plug loose @ 8800'. Pushed bridge plug to 8844'. Drld. on bridge plug fr. 8844' to 8849'. Ran 4-5/8" Klusterite shoe, wash pipe, oil jars & DC's on 2-3/8" tbg. milled on bridge plug. Ran drlg. bailer & knocked bridge plug loose & pushed to 10,014' opening up Devonian zone 5 1/2" csg. perf. fr. 9984' to 9996'. Ran tbg. & pkr. & swab tested Devonian perfs. CI to submit AFE for futher work. Performed CORT polymer squeeze on Devonian zone thru 5 1/2" csg. perf. fr. 9984' to 9996'. Swab tested. Pulled tbg. & pkr., re-ran pkr. & tbg. & set pkr. at 9907'. Swab tested.

Presently closed in pending evaluation for futher work.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED EB Fisher TITLE Supr. Adm. Ser. DATE 4-8-80

APPROVED BY [Signature] TITLE DATE APR 11 1980

CONDITIONS OF APPROVAL, IF ANY:

10 7M (Hand)

RECEIVED

APR 10 1980

OIL CONSERVATION DIV.